



report date: 2024-03-29

General information

Make	AUDI
Model	A6 TDI SE TDV
Colour	Silver
Year of manufacture	-
Top speed	136 mph
0 - 60 mph	8.3 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	180 BHP
Max. torque	379 Nm at 1.400 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-27
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT #18	2021-04-23 12:06
MOT test number	990968212264
Result	✓ Passed
Next expiry date	2022-04-22

MOT #17	2020-03-09 17:14
MOT test number	132014395413
Result	✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing 255/35/19 (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))
- Advice** Offside Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

MOT #16	2020-03-09 10:48
MOT test number	456191625373
Result	✗ Failed

- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- DANGEROUS** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- DANGEROUS** Nearside Rear Tyre has ply or cords exposed 255/35/19 (5.2.3 (d) (ii))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing 255/35/19 (5.2.3 (d) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #15**

2019-03-25 15:34

MOT test number

514712187079

Result

✓ Passed

- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 255/35/19 (5.2.3 (e))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14

2019-03-25 09:45

MOT test number

322251928372

Result

✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- MAJOR** Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 255/35/19 (5.2.3 (e))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- MAJOR** Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #13

2018-03-16 16:46

MOT test number

707710246910

Result

✓ Passed

**MOT #12** 2018-03-16 13:29**MOT test number** 642476902686**Result** ✗ Failed

- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Central Rear Seat belt locking mechanism does not secure or release (5.2.5a)

MOT #11 2017-03-03 16:41**MOT test number** 845040593871**Result** ✓ Passed

- Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear tyre side wall damage

MOT #10 2017-03-03 14:41**MOT test number** 666415964904**Result** ✗ Failed

- Advice** Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Central Rear Seat belt locking mechanism does not secure or release (5.2.5a)
- Advice** Offside Rear tyre side wall damage
- Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #9 2016-03-04 11:37**MOT test number** 117606870336**Result** ✓ Passed



MOT #8	2016-03-04 11:27
MOT test number	884708792320
Result	✗ Failed
Fail	Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)

MOT #7	2015-01-23 14:21
MOT test number	148773525093
Result	✓ Passed
Advice	Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6	2015-01-23 14:17
MOT test number	135563225044
Result	✗ Failed
Fail	Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)
Advice	Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5	2014-03-11 15:04
MOT test number	116170674467
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2013-02-27 14:46**MOT test number** 639488653055**Result** ✓ Passed**MOT #3** 2012-02-21 17:10**MOT test number** 419612952094**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both rear tyres worn unevenly on inner edges (feathering)

MOT #2 2012-02-21 15:20**MOT test number** 679272052077**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both rear tyres worn unevenly on inner edges (feathering)
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2010-12-30 13:08**MOT test number** 882354260305**Result** ✓ Passed



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-12-12
Last registration	2021-04-23
Complete history	See info



Registration #1	2007-12-12	19 mi
Registration #2	2010-12-30	63.466 mi
Registration #3	2012-02-21	84.975 mi
Registration #4	2012-02-21	84.975 mi
Registration #5	2013-02-27	98.864 mi
Registration #6	2014-03-11	105.328 mi
Registration #7	2015-01-23	111.037 mi
Registration #8	2015-01-23	111.037 mi
Registration #9	2016-03-04	117.481 mi
Registration #10	2016-03-04	117.481 mi
Registration #11	2016-03-04	117.481 mi
Registration #12	2016-03-04	117.481 mi
Registration #13	2016-03-04	117.481 mi
Registration #14	2016-03-04	117.481 mi
Registration #15	2016-03-04	117.481 mi
Registration #16	2016-03-04	117.481 mi
Registration #17	2016-03-04	117.481 mi
Registration #18	2016-03-04	117.481 mi
Registration #19	2016-03-04	117.481 mi
Registration #20	2016-03-04	117.481 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1463 mm
Length	4933 mm
Wheel base	2759 mm
Kerb weight	1725 kg
Max. allowed weight	2355 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BPP 080601