



report date: 2024-03-28

General information

Make	CITROEN
Model	C5 HDI VTR PLUS NAV
Colour	Grey
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	179 g/km
CO2 label	I







Internet history

Entry 2


Date	2021-12-24
Pictures	52
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-12-21
Pictures	28
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-14
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	56
Total items failed	12

MOT #15	2024-01-08 13:33
MOT test number	948243913335
Result	✓ Passed
Next expiry date	2025-01-14
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2024-01-08 10:42
MOT test number	328878625188
Result	✗ Failed
Advice	Nearside Rear Nail in tyre
Fail	Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #13	2023-01-13 16:20
MOT test number	712856761812
Result	✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge and outer edge (5.2.3 (e))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2023-01-13 12:22

MOT test number

647470976619

Result

✗ Failed

Fail

Central Rear Suspension pipe leaking Rubber pipe (5.3.5 (c))

Advice

Nearside Front Inner Tyre worn close to legal limit/worn on edge and outer edge (5.2.3 (e))

Fail

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail

Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail

Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2022-01-15 14:09

MOT test number

443972914126

Result

✓ Passed

MOT #10

2020-11-17 11:34

MOT test number

634161776522

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))

Advice(a) (i))
Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4**Advice**

Offside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))

Advice

Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #9

2019-06-07 09:00

MOT test number

998789061139

Result

✓ Passed

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #8**

2019-06-05 11:52

MOT test number

521845944406

Result**✗ Failed****Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Central Front bonnet does not open could not do any inspection under bonnet.**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #7**

2018-06-12 11:00

MOT test number

840111485275

Result**✓ Passed****Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Under trays fitted so unable to see some components**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Second mirror in windscreen**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #6**

2017-06-28 11:25

MOT test number

551220189542

Result

✓ Passed

- Advice** Under tray fitted so unable to see some components
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Offside Rear Outer Tyre worn close to the legal limit (4.1.E.1)
- Advice** Child seat fitted to nearside rear so unable to make full inspection of adult belt
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Nearside Rear Outer Tyre worn close to the legal limit (4.1.E.1)

MOT #5

2016-06-03 14:57

MOT test number

245984056913

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit and has chunks out the sidewall (4.1.E.1)
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front headlight reflectors
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4

2015-07-06 14:32

MOT test number

279817185129

Result

✓ Passed

- Advice** Nearside Inner Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Outer Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #3**

2014-07-08 13:39

MOT test number

847919284183

Result

✓ Passed

- Notice** Nail in offside rear tyre
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Emissions to clean for tester
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Headlamp masks/converters fitted
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2

2014-07-08 12:29

MOT test number

405689684150

Result

✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Headlamp masks/converters fitted
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nail in offside rear tyre
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Emissions to clean for tester
- Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #1	2013-07-22 11:49
MOT test number	378803303294
Result	✓ Passed
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
Notice	Headlamp masks/converters fitted
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
14 January 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	14 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-04
Last registration	2024-01-08
Complete history	See info



Registration #1	2010-09-04	8 mi
Registration #2	2013-07-22	30.563 mi
Registration #3	2014-07-08	41.136 mi
Registration #4	2014-07-08	41.136 mi
Registration #5	2015-07-06	53.049 mi
Registration #6	2016-06-03	58.632 mi
Registration #7	2017-06-28	64.479 mi
Registration #8	2018-06-12	69.488 mi
Registration #9	2019-06-05	74.257 mi
Registration #10	2020-06-05	79.257 mi
Registration #11	2021-06-05	84.257 mi
Registration #12	2022-06-05	89.257 mi
Registration #13	2023-06-05	94.257 mi
Registration #14	2024-01-08	99.257 mi
Registration #15	2024-01-08	99.257 mi
Registration #16	2024-01-08	99.257 mi
Registration #17	2024-01-08	99.257 mi
Registration #18	2024-01-08	99.257 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1479 mm
Length	4289 mm
Wheel base	2815 mm
Kerb weight	1595 kg
Max. allowed weight	2286 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYWT4004886