



report date: 2024-03-28

General information

Make	MINI
Model	ONE
Colour	Red
Year of manufacture	2015
Top speed	121 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	180 Nm at 1.400 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	108 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-11-08
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #7	2023-10-26 07:21
MOT test number	471970996567
Result	✓ Passed
Next expiry date	2024-11-08
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2022-11-01 08:37
MOT test number	929782444739
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2021-11-08 09:34
MOT test number	634780849999
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2020-11-09 15:06**MOT test number** 902639348796**Result** ✓ Passed**MOT #3** 2020-11-09 13:22**MOT test number** 983813513939**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2020-01-31 14:00**MOT test number** 279894734492**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing cracking and perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Advice** Items removed from driver's view prior to test Phone holder**Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking and perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn close to legal limit and worn on edge (5.2.3 (e))**MOT #1** 2018-10-16 11:31**MOT test number** 880726549603**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
8 November 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	GY65KHH
Plate since	2019-09-29
Current registration	GY65KHH
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-10-24
Last registration	2023-10-26
Complete history	See info



Registration #1	2015-10-24	23 mi
Registration #2	2018-10-16	11.779 mi
Registration #3	2020-01-31	15.833 mi
Registration #4	2020-11-09	17.881 mi
Registration #5	2020-11-09	17.881 mi
Registration #6	2020-11-09	17.881 mi
Registration #7	2020-11-09	17.881 mi
Registration #8	2020-11-09	17.881 mi
Registration #9	2020-11-09	17.881 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3821 mm
Wheel base	2495 mm
Kerb weight	1090 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	F3421087