



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 GO SE
Colour	White
Year of manufacture	2018
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	122 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	68.9 mpg
Consumption combined	58.9 mpg
CO2 emission	112 g/km
CO2 label	C





Internet history

Entry 2

Date	2022-01-02
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2022-01-02
Pictures	0
Listing price	View report

source: heycar.co.uk



MOT history

MOT expiry date	2025-01-04
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #4	2023-12-07 11:59
--------	------------------

MOT test number	861939241023
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-04
------------------	------------

- AdviceOffside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- AdviceNearside Front Tyre worn close to legal limit/worn on edge worn smooth on inner edge (5.2.3 (e))
- AdviceNearside washer jet inop
- AdviceNearside Rear Tyre slightly damaged/cracking or perishing mishaped close to limit (5.2.3 (d) (ii))
- AdviceNearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- AdviceNearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- AdviceOffside Front Tyre worn close to legal limit/worn on edge worn smooth on inner edge (5.2.3 (e))
- AdviceOffside Rear Tyre slightly damaged/cracking or perishing close to limit mishaped (5.2.3 (d) (ii))

**MOT #3** 2022-12-20 09:31**MOT test number** 756657516727**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing age related cracking to inner and outer sidewall (5.2.3 (d) (ii))**Advice** Rear Inner Brake pad(s) wearing thin worn close to the wear indicator (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing age related cracking to inner and outer sidewall (5.2.3 (d) (ii))**MOT #2** 2022-01-05 17:10**MOT test number** 402542496224**Result** ✓ Passed**MOT #1** 2021-03-31 08:30**MOT test number** 547793014732**Result** ✓ Passed**Advice** Tyre slightly damaged/cracking or perishing both front and rear (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
4 January 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	4 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EA18EWH
Plate since	2019-03-29
Current registration	EA18EWH
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-04-04
Last registration	2023-12-07
Complete history	See info



Registration #1	2018-04-04	13 mi
Registration #2	2021-03-31	25.377 mi
Registration #3	2023-12-07	25.377 mi
Registration #4	2023-12-07	25.377 mi
Registration #5	2023-12-07	25.377 mi
Registration #6	2023-12-07	25.377 mi
Registration #7	2023-12-07	25.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	73%
Pedestrian	79%
Safety systems	64%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1158 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4LAJM823965