



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	PROACE L2H1 HDI 1200 P/V
Colour	White
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-13
Pictures	35
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-18
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	19
Total items failed	0

MOT #7	2023-05-19 16:00
MOT test number	251817744610
Result	✓ Passed
Next expiry date	2024-05-18
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Front Windscreen wiper blade defective both sides (3.4 (b) (i))
Advice	Nearside Front Outer Suspension arm ball joint has slight play (5.3.4 (a) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #6	2021-10-14 08:15
MOT test number	677467585166
Result	✓ Passed

MOT #5	2021-04-30 11:40
MOT test number	918030689976
Result	✓ Passed

MOT #4	2021-04-30 09:19
MOT test number	926662278981
Result	✗ Failed
MAJOR	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #3** 2020-05-14 14:39**MOT test number** 523164530674**Result** ✓ Passed**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2019-12-04 10:48**MOT test number** 746983705432**Result** ✓ Passed**Advice** Tail pipe mount corroded**MOT #1** 2019-11-28 12:53**MOT test number** 837358752268**Result** ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Horn not working (7.7 (a) (ii))**DANGEROUS** Offside Front Sub-frame attachment bracket/mounting missing (5.3.3 (a) (ii))**MAJOR** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Windscreen washer not working (3.5 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Tail pipe mount corroded



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	BG65HCX
Plate since	2019-09-29
Current registration	BG65HCX
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-09-30
Last registration	2023-05-19
Complete history	See info



Registration #1	2015-09-30	14 mi
Registration #2	2019-11-28	35.534 mi
Registration #3	2019-12-04	35.535 mi
Registration #4	2020-05-14	35.771 mi
Registration #5	2021-04-30	48.074 mi
Registration #6	2022-05-20	55.277 mi
Registration #7	2022-05-20	55.277 mi
Registration #8	2022-05-20	55.277 mi
Registration #9	2023-05-19	55.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	RH04161623