





report date: 2024-03-29

## General information

Make	AUDI
Model	A4 T S LINE
Colour	Black
Year of manufacture	2008
Top speed	140 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	163 BHP
Max. torque 225 Nm at 1.950 rpr	
Engine capacity	1.781 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.1 mpg
Consumption extra urban	41.5 mpg
Consumption combined	32.8 mpg
CO2 emission	197 g/km
CO2 label	J



CarCheck.co.uk page 1/14



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-20
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	33
Total items failed	21

MOT #19	2023-07-21 09:21
MOT test number	341268573065
Result	✓ Passed
Next expiry date	2024-07-20

MOT #18	2023-07-21 09:21
MOT test number	650071086391
Result	<b>X</b> Failed
Pass with rectification	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #17	2022-06-24 08:31
MOT test number	112881944624
Result	✓ Passed
MOT #16	2022-06-24 08:30
MOT test number	268068737296
Result	<b>▼</b> Failed
Pass with rectification	Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

CarCheck.co.uk page 2/14



report date: 2024-03-29

**MOT #15** 2022-06-01 08:30

**MOT test number** 233214435634

Result X Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))

**MOT #14** 2019-10-14 13:25

MOT test number 574548737431

**Result** ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing inner side wall cracking still not deep enough to reach ply or cords, needs attention (5.2.3 (d) (ii))

Advice Child Seat fitted not allowing full inspection of adult belt

**Advice** Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both side front upper outer (5.3.4 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing side wall cracking (5.2.3 (d) (ii))

Minor Front Windscreen damaged but not adversely affecting driver's view chip on the windscreen (3.2 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both side rear (1.1.14 (a) (ii))

CarCheck.co.uk page 3/14



(a) (i))

LM57UMX

report date: 2024-03-29

MOT #13 2019-10-14 13:25

**MOT test number** 626545468017

**Result** X Failed

**Advice** Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both side front upper outer (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both side rear (1.1.14 (a) (ii))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing inner side wall cracking still not deep enough to reach ply or cords, needs attention (5.2.3 (d) (ii))

Advice Child Seat fitted not allowing full inspection of adult belt

**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Offside Front Tyre slightly damaged/cracking or perishing side wall cracking (5.2.3 (d) (ii))

Minor Front Windscreen damaged but not adversely affecting driver's view chip on the windscreen (3.2

**MOT #12** 2018-08-16 10:29

MOT test number 803603967970

Result / Passed

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated FRONT (5.3.4 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened NEEDS ATTENTION (1.1.14 (a) (ii))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated FRONT (5.3.4 (b) (i))

**MOT #11** 2017-03-14 17:08

**MOT test number** 627735287159

**Result** 
✓ Passed

**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #10 2017-03-14 17:08 MOT test number 160189833638

Result × Failed

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Pass with rectification** Front Headlamp aim too low (1.8)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification Nearside Front Headlamp aim beam image obviously incorrect bulb fitted wrong

(1.8.A.1b)

**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9** 2016-03-01 15:20

**MOT test number** 371655704141

Result \( \sqrt{Passed} \)

MOT #8 2016-03-01 11:15

**MOT test number** 595492062341

Result X Failed

**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)

**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #7 2015-02-24 11:15

MOT test number 179015755088

**Notice** Front and rearbrake discs deteriorating

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT test number

Result

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2014-02-15 10:50 **MOT** test number 706836844079 Result × Failed Offside Registration plate lamp not working (1.1.C.1d) Fail **Notice** Rear tyres unevenly worn Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Fail Nearside Registration plate lamp not working (1.1.C.1d) **Notice** Nail in offside front tyre Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b) **Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #4		2013-03-09 11:37
MOT test	number	527438963010
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #3 2012-03-30 17:41

**MOT test number** 127730592060

MOT #2 2012-03-30 11:54

MOT test number 859130192060

Result × Failed

Fail Nearside Front Headlamp aim too low (1.8)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #1** 2011-03-31 16:04

**MOT test number** 389180291007

CarCheck.co.uk page 7/14



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	20 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner histo	orv

e when this test	
For how long did the current and previous owner(s) have this AUDI? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
*************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	NK NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-02-21
Last registration	2023-07-21
Complete history	See info



Registration #1	2008-02-21	7 mi
Registration #2	2011-03-31	63.966 mi
Registration #3	2012-03-30	69.222 mi
Registration #4	2012-03-30	69.222 mi
Registration #5	2013-03-09	82.056 mi
Registration #6	2014-02-15	90.410 mi
Registration #7	2014-05-06	91.502 mi
Registration #8	2015-02-24	97.450 mi
Registration #9	2016-03-01	104.581 mi
Registration #10	2016-03-01	104.581 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		0.074
Registration #19		0.074
Registration #20		111.7177 mg

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1777 mm
Height	1391 mm
Length	4573 mm
Wheel base	2650 mm
Max. allowed weight	2020 kg

# Additional information

Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number Carcheck.co.uk	BFB 163908 page 14/14