






General information

| Make | HONDA |
|---------------------|----------------|
| Model | HR-V I-VTEC SE |
| Colour | Black |
| Year of manufacture | 2017 |
| Top speed | 116 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 1 speed CVT |

Engine & fuel consumption

| Power | 129 BHP |
|-------------------------|---------------------|
| Max. torque | 155 Nm at 4.600 rpm |
| Engine capacity | 1.498 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 52.3 mpg |
| CO2 emission | 125 g/km |
| CO2 label | D |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-11-05 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-08-24 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 10 |
| Total items failed | 0 |

| MOT #4 | | 2023-08-23 10:12 |
|---|---|----------------------|
| MOT test | number | 546278513849 |
| Result | | Passed |
| Next expi | ry date | 2024-08-24 |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Nail in tyre | |
| Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) | | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) | | n excessive movement |

| МОТ #3 | 2022-08-02 12:35 |
|-----------------|------------------|
| MOT test number | 912685034514 |
| Result | ✓ Passed |

| MOT #2 | | 2021-08-06 10:48 |
|----------|--|------------------|
| MOT test | number | 185330121130 |
| Result | | 🗸 Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |





| MOT #1 | | 2020-08-19 14:08 |
|----------|--|------------------|
| MOT test | number | 431132704906 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |



Tax & MOT check

| ✓ Taxed Tax due: 1 November 2024 | MOT Expires: 24 August 2024 |
|---|--|
| Tax status | Valid until 1 November |
| Days left | 186 |
| MOT expiry date | 24 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | E.S. |
| Туре | |

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this HONDA had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2017-08-25 |
| Last registration | 2023-08-23 |
| Complete history | See info |



| Registration #1 | 2017-08-25 | 29 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-08-19 | 11.825 mi |
| Registration #3 | 2021-08-06 | 14.932 mi |
| Registration #4 | | 11.117 esi |
| Registration #5 | | 11.777 esi |
| Registration #6 | | 11.277 mi |





Safety ratings

| NCAP rating | **** |
|----------------|------------------------|
| Adult | 86% |
| Children | 79% |
| Pedestrian | 72% |
| Safety systems | 71% |
| Overall rating | 79% |
| Video | <u>see crash video</u> |



| Dimensions & weight | |
|--|-------------------------------|
| Width | 1772 mm |
| Height | 1605 mm |
| Length | 4294 mm |
| Wheel base | 2610 mm |
| Kerb weight | 1322 kg |
| Max. allowed weight | 1790 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 50 |
| | 50 l Multi-Point Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Multi-Point Injection |
| Fuel tank capacity Fuel delivery Number of doors | Multi-Point Injection 5 |