





report date: 2024-03-28

#### General information

| Make                | ТОУОТА            |
|---------------------|-------------------|
| Model               | STARLET SE        |
| Colour              | Red               |
| Year of manufacture | 1999              |
| Top speed           | 102 mph           |
| 0 - 60 mph          | 12.5 seconds      |
| Gearbox             | 3 speed automatic |

### Engine & fuel consumption

| Power                   | 84 BHP              |
|-------------------------|---------------------|
| Max. torque             | 120 Nm at 4.200 rpm |
| Engine capacity         | 1.332 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 28.0 mpg            |
| Consumption extra urban | 42.8 mpg            |
| Consumption combined    | 35.8 mpg            |



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history


#### Entry 1

Date 2021-12-10

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## **MOT** history

| MOT expiry date    | 2023-11-29 |
|--------------------|------------|
| MOT pass rate      | 80 %       |
| MOT passed         | 16         |
| Failed MOT tests   | 4          |
| Total advice items | 16         |
| Total items failed | 17         |

| MOT #20  | 2023-11-01 11:33  |
|--|-------------------|
| MOT test number  | 513116734207      |
| Result   | <b>×</b> Failed   |
| Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c  | ))                |
| Fail Front Windscreen wiper not working (3.4 (a))  |                   |
| Fail Side repeater incorrect colour Both (4.4.3 (a))   |                   |
| Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))   |                   |
| Advice Rear Brakes imbalanced requirements only just met. It would appear that the brequires adjustment or repair. (1.2.1 (b) (i)) | oraking system    |
| Advice Exhaust noisy (8.1.1 (a))   |                   |
| Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))   |                   |
| Fail Front Direction indicator incorrect colour Both (4.4.3 (a))   |                   |
| Fail Windscreen washer not working (3.5 (a))   |                   |
| Fail Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits   | (8.2.1.2 (b))     |
| Advice Rear Wheel bearing has slight play Both (5.1.3 (a) (i))   |                   |
| Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated  | d (5.3.4 (b) (i)) |
| Advice Exhaust has a minor leak of exhaust gases Front joint (6.1.2 (a))   |                   |

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #19 2022-11-18 16:16

**MOT test number** 208918845896

**Result** ✓ Passed

MOT #18 2021-11-26 10:11

MOT test number 217345098784

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #17** 2020-11-20 11:07

**MOT test number** 829214459066

**Result** 
✓ Passed

**Advice** Rear Wheel bearing has slight play both (5.1.3 (a) (i))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #16** 2020-11-20 11:07

MOT test number 877794490304

Result X Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Rear Wheel bearing has slight play both (5.1.3 (a) (i))

**MOT #15** 2019-11-30 13:42

MOT test number 919953280862

Advice Wheel bearing has slight play both rear (5.1.3 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

| MOT #14  |  | 2018-11-30 12:47 |
|----------|--|------------------|
| MOT test | number   | 433426320386     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside slight crack but not in swept area                                |                  |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

| MOT #13   | 2018-11-30 10:25 |
|---|------------------|
| MOT test number   | 679625756601     |
| Result  | <b>X</b> Failed  |
| Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))                 |                  |
| Advice Nearside slight crack but not in swept area                                |                  |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

| MOT #12         | 2017-11-29 10:19 |
|-----------------|------------------|
| MOT test number | 878479673485     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #11         | 2016-11-26 09:54 |
| MOT test number | 715708009719     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #10         | 2015-10-23 12:45 |
| MOT test number | 186475286232     |
| Result          | ✓ Passed         |
|                 |                  |

CarCheck.co.uk page 5/13



report date: 2024-03-28

| MOT #               | 9   | 2015-10-22 13:52 |
|---------------------|---|------------------|
| MOT te              | st number   | 431802026536     |
| Result              |   | <b>×</b> Failed  |
| Fail                | Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)                                       |                  |
| Fail                | Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)            |                  |
| Fail                | Offside Rear Shock absorber has a serious fluid leak (2.7.3)                                  |                  |
| Fail                | Parking brake: efficiency below requirements (3.7.B.7)  |                  |
| Fail                | Offside Front Direction indicator incorrect colour (1.4.A.2f)                                 |                  |
| <b>Fail</b> (4.1.D. | Nearside Front Tyre has a lump, caused by separation or partial failure of its structu<br>lb) | ıre 2mm          |

| MOT #8                            | 2014-09-08 09:36 |
|-----------------------------------|------------------|
| MOT test number                   | 788631254297     |
| Result                            | ✓ Passed         |
|                                   |                  |
| MOT #7                            | 2013-06-17 11:48 |
| MOT test number                   | 628228563181     |
| Result                            | ✓ Passed         |
|                                   |                  |
| MOT #6                            | 2011-05-25 14:42 |
| MOT test number                   | 247255241428     |
| Result                            | ✓ Passed         |
| Notice Both rear tyres perrishing |                  |

| MOT #5          | 2010-05-05 12:04 |
|-----------------|------------------|
| MOT test number | 270555820471     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 6/13



report date: 2024-03-28

| MOT #4          | 2009-06-03 11:57 |
|-----------------|------------------|
| MOT test number | 444634859164     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #3          | 2008-06-03 09:45 |
| MOT test number | 270345758186     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #2          | 2007-05-29 12:45 |
| MOT test number | 860339647130     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2006-05-19 16:18 |
| MOT test number | 130429236163     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 7/13



report date: 2024-03-28

29 November 2023

#### Tax & MOT check

**MOT** expiry date



Con MOT history

Full MOT history See MOT history

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

More info >

| Owner history   |             |
|---|-------------|
| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r |             |
| *********   |             |
| ***************************************   |             |
| ************  |             |
| *********   |             |
| ***************************************   |             |
| ***************************************   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this TOYOTA had different number plates.   |             |
| Number of plates  |             |
| Current registration  | NK SIE      |
| Plate since   |             |
| Current registration  | OK SIE      |
| Plate since   |             |

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact into

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 22         |
| First mileage registration | 1999-03-16 |
| Last registration          | 2023-11-01 |
| Complete history           | See info   |



| Registration #2       2006-05-19       23.483 m         Registration #3       2007-05-29       24.430 m         Registration #4       2008-06-03       25.231 m         Registration #5       2009-06-03       25.676 m         Registration #6       2010-05-05       25.915 m         Registration #7       2011-05-25       26.275 m         Registration #8       2013-06-17       26.409 m         Registration #9       2014-09-08       29.210 m         Registration #10       2015-10-22       34.676 m                                  |                  |            |           |
|---|------------------|------------|-----------|
| Registration #3 2007-05-29 24.430 m Registration #4 2008-06-03 25.231 m Registration #5 2009-06-03 25.676 m Registration #6 2010-05-05 25.915 m Registration #7 2011-05-25 26.275 m Registration #8 2013-06-17 26.409 m Registration #9 2014-09-08 29.210 m Registration #10 2015-10-22 34.676 m Registration #11 2015-10-23 34.689 m Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #20 Registration #21 | Registration #1  | 1999-03-16 | 8 mi      |
| Registration #4 2008-06-03 25.231 m Registration #5 2009-06-03 25.676 m Registration #6 2010-05-05 25.915 m Registration #7 2011-05-25 26.275 m Registration #8 2013-06-17 26.409 m Registration #9 2014-09-08 29.210 m Registration #10 2015-10-22 34.676 m Registration #11 2015-10-23 34.689 m Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21  | Registration #2  | 2006-05-19 | 23.483 mi |
| Registration #5 2009-06-03 25.676 m Registration #6 2010-05-05 25.915 m Registration #7 2011-05-25 26.275 m Registration #8 2013-06-17 26.409 m Registration #9 2014-09-08 29.210 m Registration #10 2015-10-22 34.676 m Registration #11 2015-10-23 34.689 m Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21  | Registration #3  | 2007-05-29 | 24.430 mi |
| Registration #6 2010-05-05 25.915 in Registration #7 2011-05-25 26.275 in Registration #8 2013-06-17 26.409 in Registration #9 2014-09-08 29.210 in Registration #10 2015-10-22 34.676 in Registration #11 2015-10-23 34.689 in Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #18 Registration #18 Registration #19 Registration #19 Registration #20 Registration #20 Registration #21   | Registration #4  | 2008-06-03 | 25.231 mi |
| Registration #7 2011-05-25 26.275 m Registration #8 2013-06-17 26.409 m Registration #9 2014-09-08 29.210 m Registration #10 2015-10-22 34.676 m Registration #11 2015-10-23 34.689 m Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21  | Registration #5  | 2009-06-03 | 25.676 mi |
| Registration #8 2013-06-17 26.409 m Registration #9 2014-09-08 29.210 m Registration #10 2015-10-22 34.676 m Registration #11 2015-10-23 34.689 m Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21   | Registration #6  | 2010-05-05 | 25.915 mi |
| Registration #9       2014-09-08       29.210 m         Registration #10       2015-10-22       34.676 m         Registration #11       2015-10-23       34.689 m         Registration #12       Registration #13         Registration #14       Registration #15         Registration #16       Registration #17         Registration #18       Registration #19         Registration #20       Registration #21   | Registration #7  | 2011-05-25 | 26.275 mi |
| Registration #10 2015-10-22 34.676 m Registration #11 2015-10-23 34.689 m Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21   | Registration #8  | 2013-06-17 | 26.409 mi |
| Registration #11 2015-10-23 34.689 m Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21  | Registration #9  | 2014-09-08 | 29.210 mi |
| Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21   | Registration #10 | 2015-10-22 | 34.676 mi |
| Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21  | Registration #11 | 2015-10-23 | 34.689 mi |
| Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21   | Registration #12 |            | 11.777 es |
| Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21  | Registration #13 |            | 11.777 es |
| Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21   | Registration #14 |            | 11.777 es |
| Registration #17 Registration #18 Registration #19 Registration #20 Registration #21  | Registration #15 |            | 11.777 es |
| Registration #18 Registration #19 Registration #20 Registration #21   | Registration #16 |            | 11.777 es |
| Registration #19 Registration #20 Registration #21  | Registration #17 |            | 11.777 es |
| Registration #20 Registration #21   | Registration #18 |            | 11.777 es |
| Registration #21  | Registration #19 |            | 10.207 es |
|   | Registration #20 |            | 11.777 es |
| Registration #22  | Registration #21 |            | 11.777 es |
|   | Registration #22 |            | B.777 es  |

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

## Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 |                 |
| 50482 |                 |
| 50501 |                 |
| 50566 |                 |
| 50567 |                 |
| 50569 |                 |

# Safety ratings

| NCAP rating | <b>★本本</b> 京本   |
|-------------|-----------------|
| Video       | see crash video |



## Additional information

| -                  |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of axles    | 2                     |
| Engine number      | 4E2901407             |

CarCheck.co.uk page 13/13