

Ford



## General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Black
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G



# MOT history

MOT expiry date	2021-08-27	
MOT pass rate	90 %	
MOT passed	9	
Failed MOT tests	1	
Total advice items	29	
Total items failed	2	

MOT #10	2020-08-28 07:42
MOT test number	323009784288
Result	✓ Passed
Next expiry date	2021-08-27
Advice Offside Front front o/s drivers seat worn	

МОТ #9	2019-08-23 16:01
MOT test number	734313521238
Result	✓ Passed

MOT #8	2019-08-07 10:07
MOT test number	675982449398
Result	× Failed
FailExhaust on a vehicle fitted with a diesel particulate filter emits visible smoke(d))	e of any colour (8.2.2.2
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Exhaust emissions exceed manufacturer's specified limit 2.02 plate limit 0.5	0 (8.2.2.2 (a))
Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt	





MOT #7		2018-08-28 10:49
MOT test	number	910988603440
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)	)

MOT #6		2017-08-11 14:55
MOT test	number	433951675470
Result		✓ Passed
Advice	Offside Rear coil spring corroded (2.4.C.1b)	
Advice	Nearside Rear coil spring corroded (2.4.C.1b)	

MOT #5		2016-08-10 09:55
MOT test	number	341274148279
Result		✓ Passed
Advice	Washers weak operation	
Advice	Light corrosion to rear suspension components	
Advice	Child seats fitted to both rear seats preventing adult belt examination	

MOT #4		2015-07-16 09:11
MOT test	number	217117495153
Result		✓ Passed
Notice	Various curb damage to n/s/f tyre	
Notice	Plastic arch liners preventing full examination	
Notice	Service wear to front brake discs and pads	
Notice	Some uneven wear to front tyres (pressure)	
Notice	Light corrosion to suspension components	





MOT #3		2014-07-22 10:41
MOT test	number	195653804216
Result		✓ Passed
Notice	Light general corrosion to suspension subframes and components	
Notice	Some service wear to front brake discs	
Notice	Some wear to front suspension arm inner bushes	
Notice	Slight distortion to n/s/r wheel rim	
Notice	Both rear tyres wearing unevenly and n/s close to service limits	

MOT #2		2013-08-13 14:59
MOT test	number	389555523281
Result		✓ Passed
Notice	Service wear to front and rear brake discs	
Notice	Rear brake pads 50% approximately	
Notice	Slight distortion to n/s wheel rims	
Notice	Light corrosion to front suspension subframe and arms	

MOT #1		2012-09-03 16:49
MOT test	number	369087442205
Result		Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	





### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lange
Туре	
Damage 2	AMPL
	F Stores
Date	Nº I
Category	ante
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Plate since	





### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-09-26
Last registration	2020-08-28
Complete history	See info



Registration #1	2009-09-26	9 mi
Registration #2	2012-09-03	36.579 mi
Registration #3	2013-08-13	53.009 mi
Registration #4	2014-07-22	66.881 mi
Registration #5	2015-07-16	80.088 mi
Registration #6	2016-08-10	97.655 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.117 esi





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg
Additional information	
Fuel tank capacity	70
Evel delivery	
Fuel delivery	Direct Injection
Number of doors	Direct Injection 5
	- -

**Engine number** 

9B03425