





report date: 2024-03-29

General information

| Make | MERCEDES-BENZ | |
|---------------------|-----------------------|--|
| Model | V V 250 D AMG LINE XL | |
| Colour | Black | |
| Year of manufacture | 2017 | |
| Top speed | 129 mph | |
| 0 - 60 mph | 9.1 seconds | |
| Gearbox | 7 speed automatic | |

Engine & fuel consumption

| Power | 188 BHP |
|-------------------------|---------------------|
| Max. torque | 440 Nm at 2.400 rpm |
| Engine capacity | 2.143 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.7 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 44.8 mpg |
| CO2 emission | 166 g/km |
| CO2 label | Н |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-08-27 2

Pictures

Listing price View report





source: autotrader.co.uk

CarCheck.co.uk page 2/12



✓ Passed

MOT history

Result

| MOT expiry date | 2025-04-14 |
|--------------------|------------------|
| MOT pass rate | 92 % |
| MOT passed | 12 |
| Failed MOT tests | 1 |
| Total advice items | 12 |
| Total items failed | 2 |
| MOT #13 | 2024-04-15 09:13 |
| MOT test number | 891354014157 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-14 |
| MOT #12 | 2023-10-10 13:08 |
| MOT test number | 826142589810 |

| MOT #11 | 2023-05-17 10:14 |
|-----------------|------------------|
| MOT test number | 133285728779 |
| Result | ✓ Passed |

| MOT #10 | 2022-10-11 11:52 |
|-----------------|------------------|
| MOT test number | 142657914151 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



MOT test number

Result

Advice Front Brake disc worn, but not excessively both (1.1.14 (a) (i))

Advice Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))

Advice Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))

MOT #8 2022-04-04 10:03 **MOT** test number 246278488999 Result × Failed Front Brake pad(s) wearing thin both (1.1.13 (a) (ii)) Advice **Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i)) Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail **Advice** Rear Brake disc worn, but not excessively both (1.1.14 (a) (i)) Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail

 MOT #7
 2021-10-04 15:14

 MOT test number
 666076839865

 Result
 ✓ Passed

 MOT #6
 2021-05-10 15:47

 MOT test number
 270703254994

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

| MOT #5 | 2020-10-13 14:46 |
|-----------------|------------------|
| MOT test number | 535169730500 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/12



MOT #4

MOT test number

Result

Advice Nearside Tyre worn close to legal limit/worn on edge and offside front (5.2.3 (e))

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2

MOT test number

670566275022

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #1
 2018-09-05 11:48

 MOT test number
 992443406485

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 155 |
| MOT expiry date | 14 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| - | |
|--|--------------|
| Vehicle class | 49 |
| Band | I |
| First licence fee (12 months) | £ 645,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 1.040,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

Owner history

| Owner history | |
|--|-------------|
| For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here. | |
| ******** | |
| | |
| *************************************** | |
| *************************************** | |
| ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | |
| ************* | |
| | More info > |
| Plate changes | |
| See in this check if this MERCEDES-BENZ had different number plates. | |
| Number of plates | , |
| Current registration | NK NK |
| Plate since | |
| Current registration | NK NK |
| Plate since | |
| | |

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2017-07-31 |
| Last registration | 2024-04-15 |
| Complete history | See info |



| Registration #1 | 2017-07-31 | 12 mi |
|------------------|------------|------------|
| Registration #2 | 2018-09-05 | 12.121 mi |
| Registration #3 | 2019-03-01 | 17.158 mi |
| Registration #4 | 2019-08-19 | 26.376 mi |
| Registration #5 | 2020-02-21 | 30.022 mi |
| Registration #6 | 2020-10-13 | 32.073 mi |
| Registration #7 | 2021-05-10 | 33.979 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 91.777 esi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 91.777 esi |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | *** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1928 mm |
|---------------------|---------|
| Height | 1928 mm |
| Length | 5370 mm |
| Wheel base | 3430 mm |
| Kerb weight | 2255 kg |
| Max. allowed weight | 3100 kg |

Additional information

| Fuel tank capacity | 70 |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| CarChaelesaule | maga 12/12 |

CarCheck.co.uk page 12/12

| Number of seats | 8 |
|-----------------|----------------|
| Number of axles | 2 |
| Engine number | 65195034470226 |