





report date: 2024-03-29

General information

| Make | VAUXHALL |
|---------------------|---------------------|
| Model | CASCADA SE CDTI S/S |
| Colour | White |
| Year of manufacture | 2013 |
| Top speed | 135 mph |
| 0 - 60 mph | 9.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 165 BHP |
|-------------------------|---------------------|
| Max. torque | 350 Nm at 1.750 rpm |
| Engine capacity | 1.956 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 138 g/km |
| CO2 label | Е |



CarCheck.co.uk page 1/10




Internet history


Entry 1

Date 2022-01-24

Pictures 69

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date | 2024-07-16 |
|--------------------|------------|
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 5 |
| Total items failed | 1 |

| MOT #8 | 2023-06-23 13:32 |
|------------------|------------------|
| MOT test number | 653539726723 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-16 |

| MOT #7 | 2022-06-21 11:28 |
|-----------------|------------------|
| MOT test number | 884643913415 |
| Result | ✓ Passed |

| MOT #6 | 2021-07-17 12:52 |
|-----------------|------------------|
| MOT test number | 915020349595 |
| Result | ✓ Passed |

| MOT #5 | 2019-04-27 10:02 |
|--|------------------|
| MOT test number | 247867009395 |
| Result | ✓ Passed |
| Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) | |

| MOT #4 | 2018-04-19 14:49 |
|-----------------|------------------|
| MOT test number | 245447103523 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/10



MOT #3 2018-04-18 10:39

MOT test number 615113048285

Result × Failed

Fail Nearside Rear Lower coil spring broken (2.4.C.1a)

MOT #2 2017-09-01 11:46

MOT test number 559008934324

Result \rightarrow Passed

MOT #1 2016-09-14 11:59

MOT test number 789187820213

Advice Rear Brake pad(s) wearing thin inner pads (3.5.1g)

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1


Date
Category
Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here. | |
|---|-------------|
| | |
| ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | |
| *************************************** | |
| ********** | |
| | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Current registration | NK SIK |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 7/10



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2013-09-23 |
| Last registration | 2023-06-23 |
| Complete history | See info |



| Registration #1 | 2013-09-23 | 8 mi |
|---------------------------------|------------|-------------------------------------|
| Registration #2 | 2016-09-14 | 58.167 mi |
| Registration #3 | 2017-09-01 | 78.749 mi |
| Registration #4 | 2018-04-18 | 88.702 mi |
| Registration #5 | 2018-04-19 | 88.702 mi |
| | | |
| Registration #6 | | 11.777 es |
| Registration #6 Registration #7 | | 11.777 ea 11.777 ea |
| - | | 11.77 es 11.77 es |
| Registration #7 | | 11,777 ea 11,777 ea 11,777 ea |

More info >

CarCheck.co.uk page 9/10



Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 87% |
| Children | 72% |
| Pedestrian | 65% |
| Safety systems | 81% |
| Overall rating | 79% |
| Video | see crash video |



Dimensions & weight

| Width | 2020 mm |
|---------------------|---------|
| Height | 1443 mm |
| Length | 4696 mm |
| Wheel base | 2695 mm |
| Kerb weight | 1741 kg |
| Max. allowed weight | 2200 kg |

Additional information

| Fuel tank capacity | 56 I |
|--------------------|---------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | A20DTH -17B16492LBS |

CarCheck.co.uk page 10/10