



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Blue
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-06-27
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-31
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	20
Total items failed	3

MOT #12	2023-08-22 13:31
MOT test number	118850378278
Result	✓ Passed
Next expiry date	2024-08-31
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2022-08-30 13:16
MOT test number	486383123530
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))
Advice	Nearside Rear Nail in tyre
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2022-08-30 09:27

**MOT test number**

451722545926

**Result****✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Nail in tyre**MOT #9**

2021-09-01 14:37

**MOT test number**

832874975179

**Result****✓ Passed****MOT #8**

2021-01-20 15:56

**MOT test number**

314652665459

**Result****✓ Passed****MOT #7**

2020-01-23 14:47

**MOT test number**

861192415768

**Result****✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Signs of body work damage**Advice** Rear brake discs showing corrosion

**MOT #6** 2019-01-14 10:22**MOT test number** 227670054715**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge Tyre tread unevenly worn on inner edge. (5.2.3 (e))**Advice** Offside Front Lower Items removed from driver's view prior to test Mobile phone holder.**Advice** Front Brake disc worn, but not excessively Both sides front disc brakes have a lip on outer edges indicating some wear. (1.1.14 (a) (i))**Advice** Offside Front Brake pad(s) wearing thin Offside front brake pads. (1.1.13 (a) (ii))**MOT #5** 2017-12-27 11:33**MOT test number** 994893038182**Result** ✓ Passed**MOT #4** 2017-01-17 15:52**MOT test number** 624656446542**Result** ✓ Passed**Advice** All other tyres perished on side walls**MOT #3** 2017-01-17 09:24**MOT test number** 523402341701**Result** ✗ Failed**Advice** All other tyres perished on side walls**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #2** 2016-01-19 16:22**MOT test number** 918290116283**Result** ✓ Passed**Advice** Both rear tyres are cracking 205 55/16



MOT #1	2015-01-20 12:28
MOT test number	458840925074
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
31 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	31 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>LS12XAF</b>
Plate since	2019-06-29
Current registration	 <b>LS12XAF</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-27
Last registration	2023-08-22
Complete history	<a href="#">See info</a>



Registration #1	2012-03-27	25 mi
Registration #2	2015-01-20	17.338 mi
Registration #3	2016-01-19	27.815 mi
Registration #4	2017-01-17	38.662 mi
Registration #5	2017-01-17	38.662 mi
Registration #6	2017-12-27	51.704 mi
Registration #7	2019-01-14	68.191 mi
Registration #8	2019-01-14	68.191 mi
Registration #9	2019-01-14	68.191 mi
Registration #10	2019-01-14	68.191 mi
Registration #11	2019-01-14	68.191 mi
Registration #12	2019-01-14	68.191 mi
Registration #13	2019-01-14	68.191 mi
Registration #14	2019-01-14	68.191 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1474 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Number of axles**

2

**Engine number**

CAYCK90899