



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 D DRIVE R-DESIGN
Colour	White
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 1

Date	2022-01-15
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-22
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	87
Total items failed	6

MOT #212023-10-23 14:20

MOT test number530693643052

Result✓ Passed

Next expiry date2024-10-22

- AdviceNearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))
- AdviceNearside Front bumper damaged
- AdviceRear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- AdviceFront undertray slightly loose
- AdviceFront Integral body structure is corroded but structural rigidity is not significantly reduced radiator support badly corroded (6.1.1 (c) (i))
- AdviceFront Exhaust mounting defective (6.1.2 (a))
- AdviceOffside Rear bumper damaged
- AdviceOffside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #20**

2023-10-19 15:14

**MOT test number**

909846521109

**Result****✗ Failed****Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Offside registration plate lamp dim**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**DANGEROUS** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure distorted on inner edge (5.2.3 (d) (ii))**Advice** Offside Rear bumper damaged**Advice** Offside Rear Direction Indicator slightly discoloured (4.4.3 (a))**MAJOR** Offside Headlamp aim unable to be tested (4.1.2 (b))**Advice** Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front bumper damaged**DANGEROUS** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure distorted on inner edge (5.2.3 (d) (ii))**Advice** Front undertray slightly loose**Advice** Front Integral body structure is corroded but structural rigidity is not significantly reduced radiator support badly corroded (6.1.1 (c) (i))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))



MOT #19 2023-10-17 15:14

MOT test number 787459955371

Result ✗ Failed

**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Radiator lower support badly corroded

**MAJOR** Fuel tank leaking (6.1.3 (b) (i))

**DANGEROUS** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Front Exhaust mounting defective (6.1.2 (a))

**MAJOR** Rear Bumper insecure (6.1.4 (a) (i))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MAJOR** Offside Front Headlamp aim unable to be tested (4.1.2 (b))

**Advice** Under - trays fitted

**DANGEROUS** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Front Exhaust has a minor leak of exhaust gases Flexi pipe in weak condition (6.1.2 (a))

**Advice** Oil leak, but not excessive Transmission (8.4.1 (a) (i))

**MAJOR** Front Bumper insecure (6.1.4 (a) (i))

**MOT #18** 2022-10-21 10:56**MOT test number** 157779503262**Result** ✓ Passed**MOT #17** 2022-10-12 16:10**MOT test number** 614397746733**Result** ✗ Failed**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge stepped (5.2.3 (e))**MAJOR** Front Service brake excessively fluctuating (1.2.1 (e))**MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**DANGEROUS** Nearside Rear Anti-roll bar linkage missing (5.3.3 (a) (ii))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge stepped (5.2.3 (e))**MAJOR** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Front Exhaust mounting defective (6.1.2 (a))**MOT #16** 2022-01-25 15:39**MOT test number** 380634499930**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #15**

2022-01-17 09:11

**MOT test number**

623976383595

**Result****✗ Failed**

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MAJOR** Headlamp not working on dipped beam both lamps (4.1.1 (a) (ii))

**MAJOR** Nearside Rear Service brake excessively binding unable to check bearing for noise (1.2.1 (f))

**MAJOR** Bonnet cannot be secured in the closed position (3.1 (b) (i))

**MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))

**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MAJOR** Headlamp aim not tested both lamps (4.1.2 (b))

**Advice** Nearside Front sidelight dim

**MOT #14**

2020-10-20 12:54

**MOT test number**

953680088456

**Result****✓ Passed**

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #13**

2020-10-16 14:04

**MOT test number**

523187431716

**Result****✗ Failed****DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #12**

2019-05-21 12:26

**MOT test number**

529325983776

**Result****✓ Passed****Advice** Nearside rear brake binding slightly**Advice** Scratches in windscreen



**MOT #11** 2019-05-20 11:39**MOT test number** 191150030576**Result** ✗ Failed**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside rear brake binding slightly**MAJOR** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Scratches in windscreen**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2018-05-16 14:53**MOT test number** 584860633584**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front coil spring corroded (2.4.C.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2018-05-15 15:39**MOT test number** 707152542595**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Anti-roll bar linkage missing (2.4.G.1)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Anti-roll bar linkage missing (2.4.G.1)**Advice** Offside Front coil spring corroded (2.4.C.1b)

**MOT #8** 2017-04-28 15:11**MOT test number** 628869564589**Result** ✓ Passed**MOT #7** 2016-05-17 15:37**MOT test number** 851550685777**Result** ✓ Passed**MOT #6** 2015-03-31 11:37**MOT test number** 197100695413**Result** ✓ Passed**MOT #5** 2014-03-17 17:15**MOT test number** 565466974095**Result** ✓ Passed**MOT #4** 2014-03-17 16:30**MOT test number** 128316574030**Result** ✗ Failed**Fail** Offside Rear Tyre(s) incorrect because a lightweight or space saving wheel is fitted (4.1.A.1b)**Fail** Rear Registration plate lamp not working (1.1.C.1d)**MOT #3** 2013-08-21 09:12**MOT test number** 828733833232**Result** ✓ Passed**MOT #2** 2013-08-21 09:12**MOT test number** 909073533278**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)



MOT #1	2012-08-13 17:01
MOT test number	169036722213
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
22 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	22 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-09-22
Last registration	2023-10-23
Complete history	<a href="#">See info</a>



Registration #1	2009-09-22	19 mi
Registration #2	2012-08-13	27.906 mi
Registration #3	2013-08-21	44.021 mi
Registration #4	2014-03-17	56.195 mi
Registration #5	2014-03-17	56.195 mi
Registration #6	2015-03-31	63.158 mi
Registration #7	2016-05-17	80.696 mi
Registration #8	2017-04-28	85.637 mi
Registration #9	2018-05-15	93.436 mi
Registration #10	2018-05-16	93.436 mi
Registration #11	2019-05-20	100.904 mi
Registration #12	2020-05-20	100.904 mi
Registration #13	2020-05-20	100.904 mi
Registration #14	2020-05-20	100.904 mi
Registration #15	2020-05-20	100.904 mi
Registration #16	2020-05-20	100.904 mi
Registration #17	2020-05-20	100.904 mi
Registration #18	2020-05-20	100.904 mi
Registration #19	2020-05-20	100.904 mi
Registration #20	2020-05-20	100.904 mi
Registration #21	2020-05-20	100.904 mi
Registration #22	2023-10-23	100.904 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	704037