





report date: 2024-03-29

#### General information

Make	FORD
Model	FUSION FUSION 2
Colour	Grey
Year of manufacture	-
Top speed	101 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg



CarCheck.co.uk page 1/12




## Internet history


#### Entry 1


Date 2021-05-26

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT #17	2021-03-11 13:25
MOT test number	295990447418
Result	✓ Passed
Next expiry date	2022-03-26
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	

MOT #16		2021-03-11 13:25
MOT test number		404648579867
Result		<b>X</b> Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))		

MOT #15		2020-03-16 16:34
MOT test	number	834599170604
Result		✓ Passed
Advice	Offside Rear Nail in tyre	
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Nail in tyre	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT #14** 2020-03-16 10:20 **MOT** test number 633251830375 Result × Failed **Advice** Offside Rear Nail in tyre Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Nail in tyre Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

MOT test number

424012854866

Result

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

MOT #12

MOT test number

Passed

Advice Offside Headlamp deteriorated but light output not reduced (1.7.5a)

Advice Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

Advice All 4 tyres slight age cracking

MOT #11

MOT test number

Result

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



MOT #10	2016-02-25 12:02
MOT test number	757292030353
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1	.)
MOT #9	2015-03-05 10:59
MOT test number	418774565030
Result	✓ Passed
MOT #8	2014-02-18 13:22
MOT test number	109489344431
Result	✓ Passed
MOT #7	2013-03-12 14:12
MOT test number	755691473085
Result	<b>✓</b> Passed
MOT #6	2012-03-17 11:50
MOT test number	135487972022
Result	<b>✓</b> Passed
MOT #5	2011-02-07 16:19
MOT test number	126668431063
Result	<b>√</b> Passed
MOT #4	2010-02-04 16:08
MOT test number	624915530010
Result	<b>√</b> Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #3	2009-02-05 13:58
MOT test number	533416839037
Result	<b>✓</b> Passed
MOT #2	2008-01-26 09:33
MOT test number	152786528442
Result	✓ Passed
MOT #1	2007-02-23 15:19
MOT test number	141274857081
Result	✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Plate since

**FLO4FNN** 

report date: 2024-03-29

More info >

Owner history		
For how long did the current and previous owner(s) have this FORD? How many owners did Check it in the premium report and see all owner registrations. Download the full report he		nave?
*********		
***************************************		
************		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	UK UK	III
Plate since		
Account and the fire		

CarCheck.co.uk page 9/12



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-03-26
Last registration	2021-03-11
Complete history	See info



Registration #1	2004-03-26	27 mi
Registration #2	2007-02-23	9.258 mi
Registration #3	2008-01-26	12.467 mi
Registration #4	2009-02-05	15.171 mi
Registration #5	2010-02-04	17.779 mi
Registration #6	2011-02-07	19.152 mi
Registration #7	2012-03-17	21.499 mi
Registration #8	2013-03-12	22.604 mi
Registration #9	2014-02-18	24.073 mi
Registration #10	2015-03-05	25.752 mi
Registration #11		11.177 es
Registration #12		11.117 es
Registration #13		11.177 es
Registration #14		11.777 es
Registration #15		11.177 mi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		0.00 44
Registration #19		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
60567	
60569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Max. allowed weight	1605 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles CarCheck.co.uk	2 page 12/12

**Engine number** 

4C25139