



RENAULT

**BN60GKY**


report date: 2024-03-28

General information

Make	RENAULT
Model	LAGUNA INITIALE TOMTOM DCI
Colour	Silver
Year of manufacture	2010
Top speed	130 mph
0 - 100 km/h	9.5 seconds
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	96 kW / 131 HP / 150 BHP
Max. torque	340 Nm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.1 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-12-25
Pictures	13
Listing price	<a href="#">View report</a>



CS REPRESENTATIVE EXAMPLE	
CASH PRICE	£12,749.00
DEPOSIT	£275.00
TOTAL AMOUNT OF CREDIT	£12,474.00
TOTAL AMOUNT PAYABLE	£14,803.00
ADMINISTRATION FEE	£740.00
OPTION TO PURCHASE FEE	£10.00
FIXED INTEREST RATE	4.9% p.a.
REPRESENTATIVE APR	5.9% APR
TERM OF AGREEMENT	60 MONTHS
INITIAL REPAYMENT	£22.50
1st MONTHLY REPAYMENT	£22.50
FINAL REPAYMENT	£22.50

source: yesauto.com



MOT history

MOT expiry date	2025-04-15
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	32
Total items failed	15

MOT #18	2024-04-16 07:04
MOT test number	559409549459
Result	✓ Passed
Next expiry date	2025-04-15
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output Misting (4.1.4 (b))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output Misting (4.1.4 (b))

MOT #17	2023-03-02 14:14
MOT test number	122401294870
Result	✓ Passed
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Central Front Gearbox mounting defective

**MOT #16**

2023-03-02 09:04

**MOT test number**

791632494980

**Result****✗ Failed**

**Fail** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated Inner clip missing (6.1.7 (g) (i))

**Advice** Central Front Gearbox mounting defective

**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Rear Brakes imbalanced across an axle 33% (1.2.1 (b) (i))

**MOT #15**

2022-03-08 15:44

**MOT test number**

833456147890

**Result****✓ Passed**

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14**

2022-03-08 13:19

**MOT test number**

829938845011

**Result****✗ Failed**

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



**MOT #13** 2020-12-15 13:44**MOT test number** 856856836643**Result** ✓ Passed**MOT #12** 2020-12-08 12:52**MOT test number** 955020173389**Result** ✗ Failed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2019-11-29 12:56**MOT test number** 346311734288**Result** ✓ Passed**MOT #10** 2018-10-12 11:08**MOT test number** 138104546934**Result** ✓ Passed**MOT #9** 2017-10-17 15:30**MOT test number** 799523452765**Result** ✓ Passed

**MOT #8** 2017-10-11 08:37**MOT test number** 631840466899**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-10-14 08:53**MOT test number** 301091738466**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2016-10-14 08:53**MOT test number** 845772632251**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #5** 2015-10-19 13:29**MOT test number** 964059155356**Result** ✓ Passed**Advice** FRONT TYRE WEAR ON INNER EDGES**MOT #4** 2015-10-19 12:39**MOT test number** 667623884970**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** FRONT TYRE WEAR ON INNER EDGES**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2015-01-15 12:32**MOT test number** 219415615086**Result** ✓ Passed



MOT #2	2015-01-14 14:08
MOT test number	477074715082
Result	✗ Failed
Fail	Centre Rear Seat belt retracting mechanism defective (5.2.5b)

MOT #1	2014-01-07 11:13
MOT test number	678277004023
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
15 April 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	15 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-09-15
Last registration	2024-04-16
Complete history	<a href="#">See info</a>



Registration #1	2010-09-15	17 mi
Registration #2	2014-01-07	43.197 mi
Registration #3	2015-01-14	57.054 mi
Registration #4	2015-01-15	57.071 mi
Registration #5	2015-10-19	64.956 mi
Registration #6	2015-10-19	64.956 mi
Registration #7	2016-10-14	82.046 mi
Registration #8	2016-10-14	82.046 mi
Registration #9	2017-10-11	85.732 mi
Registration #10	2017-10-17	85.826 mi
Registration #11	2018-01-20	91.377 mi
Registration #12	2018-01-20	91.377 mi
Registration #13	2018-01-20	91.377 mi
Registration #14	2018-01-20	91.377 mi
Registration #15	2018-01-20	91.377 mi
Registration #16	2018-01-20	91.377 mi
Registration #17	2018-01-20	91.377 mi
Registration #18	2018-01-20	91.377 mi
Registration #19	2018-01-20	91.377 mi
Registration #20	2018-01-20	91.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2060 mm
Height	1445 mm
Length	4695 mm
Wheel base	2756 mm
Kerb weight	1462 kg
Max. allowed weight	2012 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	C017650