





report date: 2024-03-28

### General information

Make	FIAT
Model	500 C C LOUNGE
Colour	Red
Year of manufacture	2014
Top speed	99 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

### Internet history

Entry 1

Date 2021-06-05

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	$\sim$ $-$			
10.71	$\alpha$	h	sto	rv
101	( ) I		510	II V
	•			. ,

MOT expiry date	2025-01-23
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	9
Total items failed	4

MOT #8	2024-01-24 17:22
MOT test number	274657486843
Result	<b>✓</b> Passed
Next expiry date	2025-01-23

MOT #7	2023-06-22 14:45
MOT test number	103054323236
Result	<b>✓</b> Passed

MOT #6		2022-07-01 15:40
MOT test	number	211061024344
Result		✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #5** 2022-07-01 09:31 794961954040 **MOT** test number Result × Failed **Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b)) **Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #4

MOT test number

827935479244

Result

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #3

MOT test number

Result

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

 MOT #2
 2018-09-04 08:05

 MOT test number
 226496778902

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	23 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



EU64OJW report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this FIAT had different number plates. door of plates faste since

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-02
Last registration	2024-01-24
Complete history	See info



Registration #1	2014-09-02	11 mi
Registration #2	2017-09-01	19.890 mi
Registration #3	2018-09-04	26.483 mi
Registration #4	2020-03-17	35.736 mi
Registration #5	2021-03-11	46.776 mi
Registration #6		77,777 44
Registration #6 Registration #7		11.777 es
-		11,777 ea 11,777 ea
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	905 kg
Max. allowed weight	1320 kg

### Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number 0937673