



report date: 2024-03-28

General information

Make	KIA
Model	RIO CRDI 2 ECODYNAMICS
Colour	Black
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	15.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	170 Nm at 1.500 rpm
Engine capacity	1.120 cc
Cylinders	3
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-05-25
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-15
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	31
Total items failed	7

MOT #16	2024-01-12 15:44
MOT test number	600539436905
Result	✓ Passed
Next expiry date	2025-01-15
Advice	General under body corrosion
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #15	2024-01-12 15:44
MOT test number	557374934168
Result	✗ Failed
Pass with rectification	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	General under body corrosion

**MOT #14** 2023-01-12 10:44**MOT test number** 280629110452**Result** ✓ Passed**Minor** Suspension arm ball joint dust cover severely deteriorated n/s/f and o/s/f (5.3.4 (b) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #13** 2023-01-12 10:44**MOT test number** 759807649715**Result** ✗ Failed**Minor** Suspension arm ball joint dust cover severely deteriorated n/s/f and o/s/f (5.3.4 (b) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #12** 2022-01-06 13:07**MOT test number** 704175077794**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2021-01-08 14:44**MOT test number** 826843114010**Result** ✓ Passed**MOT #10** 2019-07-16 09:57**MOT test number** 961368468528**Result** ✓ Passed**MOT #9** 2018-10-10 11:39**MOT test number** 487014667081**Result** ✓ Passed

**MOT #8** 2018-10-09 14:28**MOT test number** 787789653365**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity inner (4.2.3 (b) (ii))**MOT #7** 2017-10-10 13:33**MOT test number** 565871697145**Result** ✓ Passed**MOT #6** 2017-10-10 13:33**MOT test number** 981840901949**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2016-10-06 12:11**MOT test number** 831982576700**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Advice** Offside Rear Nail in tyre**Advice** Undertrays fitted**Advice** Items removed from driver's view prior to test

**MOT #4**

2016-10-06 12:11

MOT test number

470232307802

Result**✗ Failed****Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Advice** Undertrays fitted**Advice** Offside Rear Nail in tyre**Advice** Items removed from driver's view prior to test**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Nail in tyre**MOT #3**

2015-10-09 08:28

MOT test number

830601214498

Result**✓ Passed****Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #2**

2014-10-15 11:17

MOT test number

245958184280

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2013-12-18 09:21
MOT test number	119392653313
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
15 January 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	15 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	NA61KVJ
Plate since	2024-03-28
Current registration	NA61KVJ
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-10-17
Last registration	2024-01-12
Complete history	See info



Registration #1	2011-10-17	27 mi
Registration #2	2013-12-18	11.335 mi
Registration #3	2014-10-15	24.301 mi
Registration #4	2015-10-09	38.951 mi
Registration #5	2016-10-06	47.397 mi
Registration #6	2016-10-06	47.397 mi
Registration #7	2017-10-10	53.288 mi
Registration #8	2017-10-10	53.288 mi
Registration #9	2018-10-09	58.131 mi
Registration #10	2019-10-09	63.077 mi
Registration #11	2019-10-09	63.077 mi
Registration #12	2019-10-09	63.077 mi
Registration #13	2019-10-09	63.077 mi
Registration #14	2019-10-09	63.077 mi
Registration #15	2019-10-09	63.077 mi
Registration #16	2019-10-09	63.077 mi
Registration #17	2019-10-09	63.077 mi
Registration #18	2019-10-09	63.077 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1293 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D3FABH300246