



General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TSI DSG
Colour	White
Year of manufacture	2009
Top speed	135 mph
0 - 60 mph	8.5 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	160 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.7 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-28
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-07
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	27
Total items failed	6

MOT #15	2023-11-10 13:43
MOT test number	598023859922
Result	✓ Passed
Next expiry date	2024-12-07
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2022-11-28 16:40
MOT test number	867232604349
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge Both Sides (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13** 2021-11-20 10:45**MOT test number** 693518589233**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #12** 2020-12-08 17:32**MOT test number** 666611218027**Result** ✓ Passed**MOT #11** 2019-11-15 13:52**MOT test number** 774991049563**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn low and scuffs/nicks in sidewall (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #10** 2019-11-15 11:34**MOT test number** 755111128474**Result** ✗ Failed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn low and scuffs/nicks in sidewall (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure Split to cords on inner edge and worn very low (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9** 2018-11-27 16:19**MOT test number** 789974497022**Result** ✓ Passed**MOT #8** 2018-11-27 15:04**MOT test number** 913936288609**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #7** 2017-11-13 15:26**MOT test number** 749179781254**Result** ✓ Passed

**MOT #6** 2017-11-13 12:08**MOT test number** 443466117970**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #5** 2016-11-28 10:30**MOT test number** 372688735746**Result** ✓ Passed**MOT #4** 2015-11-16 12:35**MOT test number** 753649304193**Result** ✓ Passed**MOT #3** 2014-11-17 12:31**MOT test number** 255051824323**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2013-11-25 10:51**MOT test number** 866799823327**Result** ✓ Passed**MOT #1** 2012-11-12 14:35**MOT test number** 536627812349**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
7 December 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	7 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KM59RHE
Plate since	2024-03-29
Current registration	 KM59RHE
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-12-07
Last registration	2023-11-10
Complete history	See info



Registration #1	2009-12-07	24 mi
Registration #2	2012-11-12	21.016 mi
Registration #3	2013-11-25	26.090 mi
Registration #4	2014-11-17	32.084 mi
Registration #5	2015-11-16	37.146 mi
Registration #6	2016-11-28	44.028 mi
Registration #7	2017-11-13	50.344 mi
Registration #8	2017-11-13	50.344 mi
Registration #9	2018-11-27	57.594 mi
Registration #10	2019-11-27	64.844 mi
Registration #11	2020-11-27	72.094 mi
Registration #12	2021-11-27	79.344 mi
Registration #13	2022-11-27	86.594 mi
Registration #14	2023-11-27	93.844 mi
Registration #15	2024-11-27	101.094 mi
Registration #16	2025-11-27	108.344 mi
Registration #17	2026-11-27	115.594 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1439 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	BZB 108464