



H383ATO

report date: 2024-03-28

General information

Make	LOTUS
Model	ELAN ELAN SE
Colour	Red
Year of manufacture	1991
Top speed	137 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	198 Nm at 4.200 rpm
Engine capacity	1.588 cc
Cylinders	4
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-18
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-03
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	29
Total items failed	2

MOT #17	2024-01-04 08:55
MOT test number	474806221806
Result	✓ Passed
Next expiry date	2025-01-03

MOT #16	2022-08-16 07:52
MOT test number	356654191507
Result	✓ Passed

MOT #15	2021-04-29 07:44
MOT test number	260379336142
Result	✓ Passed

MOT #14	2019-04-18 07:49
MOT test number	781689088908
Result	✓ Passed

Advice Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13**

2019-04-16 13:22

MOT test number

926274137535

Result

✗ Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #12**

2015-10-14 14:46

MOT test number

870544106160

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit very close 1.6mm - 205/50/15 (4.1.E.1)**Advice** Many metal brake pipe greased limiting inspection**Advice** Nearside Rear Tyre worn close to the legal limit very close 1.6mm - 205/50/15 (4.1.E.1)**Advice** Rear service brake only just met the requirements would advise some adjustment**Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)**Advice** Offside Front Tyre worn close to the legal limit very close 1.6mm - 205/50/15 (4.1.E.1)**Advice** Vehicle underside has been undersealed limiting inspection**Advice** Offside Rear Tyre worn close to the legal limit very close 2.0mm - 205/50/15 (4.1.E.1)

**MOT #11** 2014-04-14 15:04**MOT test number** 278524004484**Result** ✓ Passed**Advice** Nearside Rear wheel bearing has slight play (2.6.2)**Advice** Offside Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Notice** Play in steering rack inner joint(s)**MOT #10** 2013-01-05 10:01**MOT test number** 797505003022**Result** ✓ Passed**MOT #9** 2011-11-19 14:32**MOT test number** 969503321310**Result** ✓ Passed**Notice** Both rear sus arms corroded**Notice** Rear brake imbalance**MOT #8** 2010-11-02 12:19**MOT test number** 581066600310**Result** ✓ Passed**Advice** Offside front brake grabbing slightly (3.7.A.2b)**Advice** Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #7** 2009-10-27 11:17**MOT test number** 132490809354**Result** ✓ Passed**Notice** Heavey underseal obscuring some components

**MOT #6** 2009-10-26 16:57**MOT test number** 300339399201**Result** ✗ Failed**Notice** Heavy underseal obscuring some components**Fail** Rear registration plate deteriorated (6.3.1d)**MOT #5** 2008-10-10 14:59**MOT test number** 234774588273**Result** ✓ Passed**MOT #4** 2007-10-04 11:17**MOT test number** 992477577276**Result** ✓ Passed**Notice** Rear number plate slightly deteriorated**Notice** Near side front outer boot deteriorated slight**MOT #3** 2007-09-19 12:18**MOT test number** 282082067221**Result** ✓ Passed**MOT #2** 2006-09-11 17:55**MOT test number** 643294056223**Result** ✓ Passed**MOT #1** 2006-08-15 10:15**MOT test number** 701207726277**Result** ✗ Failed**Fail** Brakes imbalanced across an axle (3.7.B.5b)



Damage history

Check the damage history for this LOTUS. See if, where and when this LOTUS had damage and the car repair costs. We also check if this LOTUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LOTUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this LOTUS? How many owners did this LOTUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LOTUS had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this LOTUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LOTUS has been settled.

If not, and you buy this LOTUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LOTUS is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	1991-05-01
Last registration	2024-01-04
Complete history	See info



Registration #1	1991-05-01	16 mi
Registration #2	2006-08-15	67.122 mi
Registration #3	2006-09-11	67.133 mi
Registration #4	2007-09-19	68.149 mi
Registration #5	2007-10-04	68.163 mi
Registration #6	2008-10-10	69.833 mi
Registration #7	2009-10-26	70.454 mi
Registration #8	2009-10-27	70.454 mi
Registration #9	2010-11-02	71.719 mi
Registration #10	2011-11-19	72.511 mi
Registration #11	2012-05-22	73.277 mi
Registration #12	2013-05-22	74.277 mi
Registration #13	2014-05-22	75.277 mi
Registration #14	2015-05-22	76.277 mi
Registration #15	2016-05-22	77.277 mi
Registration #16	2017-05-22	78.277 mi
Registration #17	2018-05-22	79.277 mi
Registration #18	2019-05-22	80.277 mi
Registration #19	2020-05-22	81.277 mi

More info >



Dimensions & weight

Width	1885 mm
Height	1230 mm
Length	3803 mm

Additional information

Engine number	0051694
---------------	---------