





report date: 2024-03-29

General information

Make	MINI
Model	MINI (R57) COOPER D
Colour	Blue
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.3 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

		1
ᆮ	HLIV	-

Life y 1	
Date	2021-07-01
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-14
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	11
Total items failed	5

MOT #13	2023-07-15 09:05
MOT test number	217157517950
Result	✓ Passed
Next expiry date	2024-07-14
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #12		2023-07-15 09:04
MOT test number		800314153728
Result		X Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))		
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #11	2022-07-13 11:54
MOT test number	438874423845
Result	✓ Passed

MOT #10		2022-07-13 11:54
MOT test number		604252108624
Result		× Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9 2021-07-14 12:52

MOT test number 282726802582

Result Passed

MOT #8 2021-07-14 10:58

MOT test number 109500758955

Result × Failed

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

Advice Nearside Rear Lower Coil spring corroded (5.3.1 (b) (i))

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Advice Offside Rear Outer Coil spring corroded (5.3.1 (b) (i))

MOT #7 2020-07-06 13:19

MOT test number 162569320932

Result \rightarrow Passed

Advice Brake pipes above fuel tank not visable

Advice Plastic under trays fitted obscuring some components

MOT #6 2019-07-12 09:04

MOT test number 592610431043

Result

Passed

Advice Diesel smoke emissions reading to low for d/s/m to read or pick up

MOT #5 2018-07-11 16:48

MOT test number 487958260221

Result ✓ Passed

Advice Items removed from driver's view prior to test

CarCheck.co.uk page 4/12



MOT #4

MOT test number

611681958993

Result

MOT #3

MOT test number

2016-07-13 11:38

MOT test number

527593830866

Result

Advice Engine cover fitted under trays fitted

MOT #2	2015-10-12 10:53
MOT test number	895396748416
Result	✓ Passed
MOT #1	2014-10-16 12:55
MOT test number	336219184285
Result	✓ Passed
Notice Front wiper blades split	

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	14 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report h		e?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-10-20
Last registration	2023-07-15
Complete history	See info



Registration #1	2011-10-20	13 mi
Registration #2	2014-10-16	49.890 mi
Registration #3	2015-10-12	52.268 mi
Registration #4	2016-07-13	53.766 mi
Registration #5	2017-06-26	55.960 mi
Registration #6	2018-07-11	57.794 mi
Registration #7	2019-07-12	73.559 mi
Registration #8	2020-07-06	96.395 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1200 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/1