



report date: 2024-03-29

General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Black
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	550 Nm at 1.500 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.8 mpg
CO2 emission	239 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-10-22
Pictures	21
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-12-08
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	23
Total items failed	5

MOT #17	2022-12-09 15:21
MOT test number	611023450141
Result	✓ Passed
Next expiry date	2023-12-08
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2022-12-01 09:41**MOT test number** 660974837402**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Brake hose excessively damaged (1.1.12 (b) (ii))**Minor** Offside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**DANGEROUS** Nearside Rear Road wheel fractured (5.2.2 (a))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Minor** Offside Front Brake hose slightly damaged (1.1.12 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2021-11-19 14:28**MOT test number** 477622811110**Result** ✓ Passed

**MOT #14** 2021-11-16 11:02**MOT test number** 848376628091**Result** ✗ Failed

DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))

MAJOR Offside Front Road wheel fixing missing (5.2.1 (a) (i))

MAJOR Offside Rear Road wheel fixing missing (5.2.1 (a) (i))

MOT #13 2019-11-25 14:48**MOT test number** 612754029839**Result** ✓ Passed**MOT #12** 2019-04-13 11:09**MOT test number** 972176515942**Result** ✓ Passed**MOT #11** 2018-03-07 13:26**MOT test number** 823908486820**Result** ✓ Passed**MOT #10** 2017-02-02 10:47**MOT test number** 522786721565**Result** ✓ Passed**MOT #9** 2016-10-06 09:48**MOT test number** 341853785806**Result** ✓ Passed

**MOT #8** 2016-10-06 09:48**MOT test number** 105907843586**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #7** 2016-01-06 11:13**MOT test number** 693434023815**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-01-09 11:50**MOT test number** 177869505448**Result** ✓ Passed**MOT #5** 2014-01-13 10:38**MOT test number** 546383514003**Result** ✓ Passed**MOT #4** 2013-01-10 14:12**MOT test number** 646920113015**Result** ✓ Passed

**MOT #3** 2013-01-10 13:08**MOT test number** 825480413058**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-01-12 11:59**MOT test number** 467742512077**Result** ✓ Passed**MOT #1** 2012-01-12 11:59**MOT test number** 878962112055**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-12-31
Last registration	2022-12-09
Complete history	See info



Registration #1	2008-12-31	24 mi
Registration #2	2012-01-12	23.021 mi
Registration #3	2013-01-10	31.287 mi
Registration #4	2013-01-10	31.287 mi
Registration #5	2014-01-13	40.164 mi
Registration #6	2015-01-09	49.180 mi
Registration #7	2016-01-06	58.632 mi
Registration #8	2016-10-06	64.520 mi
Registration #9	2016-10-06	64.520 mi
Registration #10	2017-01-01	75.000 mi
Registration #11	2017-01-01	75.000 mi
Registration #12	2017-01-01	75.000 mi
Registration #13	2017-01-01	75.000 mi
Registration #14	2017-01-01	75.000 mi
Registration #15	2017-01-01	75.000 mi
Registration #16	2017-01-01	75.000 mi
Registration #17	2017-01-01	75.000 mi
Registration #18	2017-01-01	75.000 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3150 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	CAS 059725