





report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2014
Top speed	120 mph
0 - 100 km/h	10.9 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12




report date: 2024-03-28

Internet history

Entry 1

Date	2021-08-12	
Pictures	1	
Listing price	View report	



source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-04-29
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	11
Total items failed	11

MOT #10	2024-04-20 11:24
MOT test number	317413860223
Result	X Failed
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, r ingress of dirt (6.1.7 (g) (ii))	no longer prevents the
Fail Offside Front Tyre has ply or cords exposed 225/50/17 (5.2.3 (d) (ii))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or (i))	r light sources (4.7.1 (b)

MOT #9	2023-04-24 09:56
MOT test number	581536238445
Result	✓ Passed
MOT #8	2022-04-25 11:18
MOT test number	344687560573
Result	✓ Passed
Advice Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7 2021-04-08 10:13

MOT test number 267719356349

Result \rightarrow Passed

MOT #6 2021-04-06 09:05

MOT test number 408769787530

Result ★ Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure also cords exposed on inner edge (5.2.3 (d) (ii))

Fail Central Rear Seat belt buckle not functioning as intended central rear seat belt buckle (7.1.2 (d))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge also perishing (5.2.3 (e))

MOT #5 2020-04-30 13:26

MOT test number 779646906439

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

MOT #4 2019-02-12 16:46

MOT test number 750465739763

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3 2019-02-08 15:56 **MOT** test number 691933755422 Result **X** Failed Fail Central Rear Seat belt buckle not functioning as intended (7.1.2 (d)) Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b)) Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Fail Central Stop lamp(s) not working (4.3.1 (a) (ii)) **Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Electronic stability control warning lamp indicates a fault (7.12 (e))

MOT test number

807055206670

Result

Advice (2.4.G.2)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Front brake pads are starting to wear thin

MOT #1	2017-02-09 16:36
MOT test number	120179352785
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	29 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK ZIS
Plate since	
Current registration	UK UK
Plate since	
	Moro info

CarCheck.co.uk page 9/12



GX14NSF report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



GX14NSF report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-29
Last registration	2024-04-20
Complete history	See info



Registration #1	2014-03-29	7 mi
Registration #2	2017-02-09	42.070 mi
Registration #3	2018-01-22	50.570 mi
Registration #4	2019-02-08	62.652 mi
Registration #5	2019-02-12	62.669 mi
Registration #6	2020-04-30	74.682 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1688 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles2Engine numberET47075