



report date: 2024-03-29

General information

Make	KIA
Model	SEDONA LS
Colour	Blue
Year of manufacture	2008
Top speed	120 mph
0 - 60 mph	16.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	343 Nm at 4.500 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.0 mpg
Consumption extra urban	40.4 mpg
Consumption combined	31.4 mpg
CO2 emission	224 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-11-05
Pictures	25
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-08-30
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	38
Total items failed	19

MOT #21	2023-08-12 09:00
MOT test number	116837831066
Result	✓ Passed
Next expiry date	2024-08-30
Advice	Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #20	2022-08-16 14:13
MOT test number	896863878487
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #19	2021-08-31 16:33
MOT test number	909893073048
Result	✓ Passed

**MOT #18** 2021-08-31 16:33**MOT test number** 549066963053**Result** ✗ Failed**Pass with rectification** Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #17** 2020-08-28 10:45**MOT test number** 621445312570**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Power steering component has slight seepage from a component (2.1.5 (a))**MOT #16** 2020-08-28 10:45**MOT test number** 500187403972**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Power steering component has slight seepage from a component (2.1.5 (a))**MOT #15** 2019-07-19 09:21**MOT test number** 837041409996**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #14**

2018-07-13 15:32

MOT test number

387472896459

Result

✓ Passed

Advice Nearside Front Earth Strap Broken On Gearbox**Minor** Central Front Windscreen damaged but not adversely affecting driver's view Chip In Windscreen (3.2 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Oil Leak**Advice** Central Rear Wiper Torn**MOT #13**

2018-07-13 10:25

MOT test number

924483330413

Result

✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Central Rear Wiper Torn**Fail** Nearside Side repeater incorrect colour (4.4.3 (a))**Advice** Nearside Front Earth Strap Broken On Gearbox**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Front Service brake excessively fluctuating Both Front (1.2.1 (e))**Minor** Central Front Windscreen damaged but not adversely affecting driver's view Chip In Windscreen (3.2 (a) (i))**Advice** Oil Leak**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Side repeater incorrect colour (4.4.3 (a))

**MOT #12** 2017-07-21 14:38**MOT test number** 509044663845**Result** ✓ Passed**MOT #11** 2017-07-14 09:25**MOT test number** 343282763026**Result** ✗ Failed

- Fail** Power steering component(s) leaking steering rack (2.3.3b)
- Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #10 2016-06-17 13:58**MOT test number** 873533935189**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #9 2016-06-17 09:47**MOT test number** 499538822570**Result** ✗ Failed

- Fail** Nearside Headlamp aim too low (1.8)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Headlamp aim too low (1.8)

MOT #8 2015-09-05 10:39**MOT test number** 189323898445**Result** ✓ Passed

**MOT #7** 2014-07-14 11:48**MOT test number** 406565394101**Result** ✓ Passed

- Notice** Oil at minimum
- Notice** Under-trays fitted obscuring some underside components
- Notice** Oil leak

MOT #6 2013-10-11 17:38**MOT test number** 836714683242**Result** ✓ Passed**MOT #5** 2013-10-11 12:40**MOT test number** 339714483246**Result** ✗ Failed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Oil leak
- Fail** Power steering fluid level below minimum (2.3.1)
- Notice** Front tyres bald inner edge, nearside rear low outer edge & offside rear on wear limit
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Notice** Front & rear inner brake pads appear low

MOT #4 2012-10-16 13:21**MOT test number** 139250992255**Result** ✓ Passed

**MOT #3** 2012-10-16 09:41**MOT test number** 337520892210**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Near side rear tyre puncher on shoulder of tyre**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-10-26 09:42**MOT test number** 596559091283**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2011-10-26 09:42**MOT test number** 548659591224**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

X

Untaxed

Tax expired:
20 October 2023

✓

MOT

Expires:
30 August 2024

Tax status	Expired at 20 October 2023
Days left	193 days too late
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	LC58JJV
Plate since	2024-03-29
Current registration	LC58JJV
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-10-31
Last registration	2023-08-12
Complete history	See info



Registration #1	2008-10-31	27 mi
Registration #2	2011-10-26	30.480 mi
Registration #3	2012-10-16	39.655 mi
Registration #4	2012-10-16	39.655 mi
Registration #5	2013-10-11	51.719 mi
Registration #6	2013-10-11	51.719 mi
Registration #7	2014-07-14	59.224 mi
Registration #8	2015-09-05	69.198 mi
Registration #9	2016-06-17	72.683 mi
Registration #10	2016-06-17	72.683 mi
Registration #11	2017-07-14	77.620 mi
Registration #12	2018-06-20	82.557 mi
Registration #13	2019-06-20	87.494 mi
Registration #14	2020-06-20	92.431 mi
Registration #15	2021-06-20	97.368 mi
Registration #16	2022-06-20	102.305 mi
Registration #17	2023-06-20	107.242 mi
Registration #18	2023-06-20	107.242 mi
Registration #19	2023-06-20	107.242 mi
Registration #20	2023-06-20	107.242 mi
Registration #21	2023-06-20	107.242 mi
Registration #22	2023-06-20	107.242 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1985 mm
Height	1815 mm
Length	4810 mm
Wheel base	2890 mm
Kerb weight	2189 kg
Max. allowed weight	2920 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	J3 8 262031