



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EVO MULTIAIR SPORTING
Colour	Black
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	135 BHP
Max. torque	206 Nm at 1.750 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D





MOT history

MOT expiry date	2024-07-01
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	23
Total items failed	29

MOT #18	2023-06-29 14:06
MOT test number	497339173543
Result	✓ Passed
Next expiry date	2024-07-01
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17	2023-06-28 09:37
MOT test number	386154072884
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #16	2022-07-02 11:14
MOT test number	928515578998
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #15**

2022-06-24 10:08

MOT test number

617934556011

Result**✗ Failed**

Fail Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Parking brake inoperative on one side low effort (1.4.1 (a))

Fail Offside Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14

2021-03-08 09:22

MOT test number

690303611281

Result**✓ Passed**

Advice Rear parking brake only just met requirements

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #13

2020-02-18 12:54

MOT test number

958757141166

Result**✓ Passed**

**MOT #12** 2020-02-18 12:54**MOT test number** 272530069235**Result** ✗ Failed**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2019-02-18 16:21**MOT test number** 986131944236**Result** ✓ Passed**MOT #10** 2018-02-19 14:16**MOT test number** 760048843918**Result** ✓ Passed**MOT #9** 2018-02-16 16:31**MOT test number** 103911858482**Result** ✗ Failed**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #8** 2017-05-09 14:04**MOT test number** 942832013431**Result** ✓ Passed**Advice** Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust corroded

**MOT #7**

2017-04-24 15:07

MOT test number

870418610898

Result**✗ Failed****Advice** Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Advice** Exhaust corroded**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Fail** Offside Front Brake hose inappropriately repaired (3.6.A.3)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6**

2016-04-29 06:40

MOT test number

420349758688

Result**✓ Passed**

**MOT #5**

2016-04-26 13:47

MOT test number

318767977988

Result**✗ Failed****Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Front Wipers smearing windscreen**Fail** Rear brakes release unevenly (3.7.B.4)**Fail** Nearside Headlamp aim too high (1.8)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear brake application uneven (3.7.B.2)**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Offside Headlamp aim too high (1.8)**MOT #4**

2015-04-13 16:38

MOT test number

505453605100

Result**✓ Passed****Notice** Rear exhaust outer skin corroded**Advice** Nearside Inner Front Brake pad(s) wearing thin (3.5.1g)**MOT #3**

2015-04-13 09:27

MOT test number

956333005154

Result**✗ Failed****Notice** Items removed from driver's view prior to test**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Inner Front Brake pad(s) wearing thin (3.5.1g)**Notice** Rear exhaust outer skin corroded**Fail** Nearside Front wheel bearing rough when rotated (2.5.A.2)



MOT #2	2014-04-10 16:50
MOT test number	607800804128
Result	✓ Passed

MOT #1	2013-04-10 13:56
MOT test number	909440003144
Result	✓ Passed
<div><div>Notice</div>Both front tyres starting to become cracked and perished</div> <div><div>Notice</div>Items removed from driver's view prior to test</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
1 July 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	1 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-04-15
Last registration	2023-06-29
Complete history	See info



Registration #1	2010-04-15	22 mi
Registration #2	2013-04-10	20.007 mi
Registration #3	2014-04-10	36.252 mi
Registration #4	2015-04-13	48.600 mi
Registration #5	2015-04-13	48.600 mi
Registration #6	2016-04-26	55.215 mi
Registration #7	2016-04-29	55.218 mi
Registration #8	2017-04-24	62.594 mi
Registration #9	2017-05-09	62.595 mi
Registration #10	2018-02-16	66.105 mi
Registration #11	2019-05-29	75.377 mi
Registration #12	2019-05-29	75.377 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi
Registration #18	2019-05-29	75.377 mi
Registration #19	2019-05-29	75.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1155 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	1520797