



SA55LCW

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 350 MWB DRW C/C
Colour	White
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2020-11-15
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	35
Total items failed	23

MOT #19	2019-11-16 16:05
MOT test number	842199854196
Result	✓ Passed
Next expiry date	2020-11-15

**MOT #18**

2018-08-14 09:56

MOT test number

936021078202

Result**✗ Failed**

- Fail** Exhaust emissions test aborted because smoke levels are significantly in excess of the specified limit values 0.90 (8.2.2.2 (f))
- Fail** Offside Position lamp not working All side marker lights (4.2.1 (a))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Nearside Rear Inner Tyre seriously under inflated
- Advice** Nearside Rear Inner Nail in tyre
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Fail** Nearside Position lamp not working All Side marker lights (4.2.1 (a))
- Fail** Nearside Front Upper Position lamp not working (4.2.1 (a))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))
- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Fail** Driver's seat insecure (6.2.5 (a) (ii))

MOT #17

2017-08-18 15:19

MOT test number

254413301197

Result**✓ Passed**

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)

**MOT #16**

2017-08-07 11:01

MOT test number

637614827806

Result

✗ Failed

Fail Offside Front Seat belt anchorage prescribed area is excessively corroded Inner and outer sills holed. (5.2.6)

Advice Nearside Play in steering rack inner joint(s)

Fail Nearside Front Seat belt anchorage prescribed area is excessively corroded Inner and outer sills holed. (5.2.6)

Advice Oil leak Engine.

MOT #15

2016-08-17 14:56

MOT test number

737327278653

Result

✓ Passed

Advice Offside Rear Anti-roll bar linkage has slight play in a pin/bush Link rod (2.4.G.2)

MOT #14

2016-08-15 10:41

MOT test number

324696932703

Result

✗ Failed

Fail Nearside front brake binding (3.7.B.1)

Advice Nearside Rear Inner Tyre worn close to the legal limit 2.4mm 185/75r16c (4.1.E.1)

Advice Offside Rear Outer Tyre worn close to the legal limit 1.9mm (4.1.E.1)

Fail Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Rear Anti-roll bar linkage has slight play in a pin/bush Link rod (2.4.G.2)

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Rear Lower Tyre worn close to the legal limit 1.7mm (4.1.E.1)

Fail Nearside Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement D bush (2.4.G.2)

**MOT #13** 2015-08-17 15:16**MOT test number** 713991491750**Result** ✓ Passed

- Advice** Front both steps corroded and holed on inner side
- Advice** Rear Tyre worn close to the legal limit all (4.1.E.1)
- Advice** Slight engine oil leak
- Advice** Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement d bushes (2.4.G.2)

MOT #12 2014-08-15 17:49**MOT test number** 329097724245**Result** ✓ Passed

- Notice** O/s step holed

MOT #11 2014-08-15 17:29**MOT test number** 357227424228**Result** ✗ Failed

- Notice** O/s step holed
- Fail** Offside Seat belt flexible stalk damaged likely to lead to failure under load (5.2.4a)
- Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)

MOT #10 2013-11-04 15:50**MOT test number** 439858203387**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Rear handbrake cables outer casing split
- Notice** Play in steering rack inner joint(s)
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #9** 2013-11-04 15:50**MOT test number** 695298303311**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Rear handbrake cables outer casing split**Notice** Play in steering rack inner joint(s)**Pass with rectification** Nearside Rear Tyre side walls on a twin fitment are contacting each other (4.1.D.3)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #8** 2012-10-16 17:01**MOT test number** 529800592217**Result** ✓ Passed**MOT #7** 2012-10-16 08:54**MOT test number** 468380092273**Result** ✗ Failed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Ball joint has excessive play (2.2.B.1f)**MOT #6** 2011-10-31 12:50**MOT test number** 528824301340**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2010-11-02 04:40**MOT test number** 280396100371**Result** ✗ Failed**Pass with rectification** Nearside Front Upper Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2010-11-02 04:40**MOT test number** 542306900397**Result** ✓ Passed**MOT #3** 2009-11-09 19:16**MOT test number** 193133419307**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Upper Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Brake pedal anti-slip provision incomplete (3.3.A.1b)**Pass with rectification** Nearside Rear fog lamp not working (1.3.2b)**MOT #2** 2009-11-09 19:16**MOT test number** 482173219438**Result** ✓ Passed**MOT #1** 2008-09-02 16:33**MOT test number** 163386448298**Result** ✓ Passed**Notice** Rear exhaust bracket loose**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
1 June 2020

✕
MOT

Expired:
15 November 2020

Tax status	Expired at 1 June 2020
Days left	1428 days too late
MOT expiry date	15 November 2020
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2005-10-18
Last registration	2019-11-16
Complete history	See info



Registration #1	2005-10-18	29 mi
Registration #2	2008-09-02	49.430 mi
Registration #3	2009-11-09	70.564 mi
Registration #4	2010-11-02	86.859 mi
Registration #5	2011-10-31	102.883 mi
Registration #6	2012-10-16	117.146 mi
Registration #7	2012-10-16	117.146 mi
Registration #8	2019-11-16	117.146 mi
Registration #9	2019-11-16	117.146 mi
Registration #10	2019-11-16	117.146 mi
Registration #11	2019-11-16	117.146 mi
Registration #12	2019-11-16	117.146 mi
Registration #13	2019-11-16	117.146 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	5C67224