





report date: 2024-03-28

General information

| Make | VOLKSWAGEN |
|---------------------|-------------------|
| Model | POLO GTI DSG |
| Colour | White |
| Year of manufacture | 2017 |
| Top speed | 146 mph |
| 0 - 100 km/h | 6.7 seconds |
| 0 - 60 mph | 6.7 seconds |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| Power | 141 kW / 192 HP / 189 BHP |
|-------------------------|---------------------------|
| Max. torque | 250 Nm at 1.300 rpm |
| Engine capacity | 1.798 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 39.2 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-09-24

Pictures 24

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-08-25 |
|--------------------|------------|
| MOT pass rate | 71 % |
| MOT passed | 5 |
| Failed MOT tests | 2 |
| Total advice items | 3 |
| Total items failed | 2 |

| MOT #7 2 | 023-08-10 09:41 |
|--------------------------------------------------------------------------------------------|-----------------|
| MOT test number | 579027449836 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-25 |
| Advice Front Tyre worn close to legal limit/worn on edge both inner edges bald (5.2.3 (e)) | |

| MOT #6 | 2023-08-05 09:38 |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| MOT test number | 221144132899 |
| Result | X Failed |
| Advice Front Tyre worn close to legal limit/worn on edge both inner edges bald (5.2.3 (a) Fail Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i) | |

| MOT #5 | 2022-08-26 08:39 |
|-----------------------------------------------------------------------------------|------------------|
| MOT test number | 704965104240 |
| Result | ✓ Passed |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |

| MOT #4 | 2021-09-29 16:35 |
|-----------------|------------------|
| MOT test number | 586342591638 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



FL17AOV

report date: 2024-03-28

MOT test number

Result

MOT test number

360051823088

Result

MOT #2

2021-03-12 12:18

MOT test number

381060311553

Result

Pass with rectification
Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

| MOT #1 | 2020-02-06 15:58 |
|-----------------|------------------|
| MOT test number | 483694932323 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 May |
|------------------|-------------------|
| Days left | 367 |
| MOT expiry date | 25 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-----------------------------------------|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 5/11



FL17AOV


report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



| Owner history | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here. | |
| ********* | |
| *************************************** | |
| | |
| | |
| | |
| *************************************** | |
| Plate changes | More info > |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | NK. |
| Plate since | |
| Current registration | OK SIN |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2017-03-03 |
| Last registration | 2023-08-10 |
| Complete history | See info |



| Registration #1 | 2017-03-03 | 28 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-02-06 | 28.913 mi |
| Registration #3 | 2021-03-12 | 36.499 mi |
| Registration #4 | 2021-03-12 | 36.499 mi |
| Registration #5 | | 91.777 esi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | D.777 es |

More info >

CarCheck.co.uk page 10/11




Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 86% |
| Pedestrian | 41% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1901 mm |
|---------------------|---------|
| Height | 1450 mm |
| Length | 3983 mm |
| Wheel base | 2468 mm |
| Kerb weight | 1180 kg |
| Max. allowed weight | 1710 kg |

Additional information

| Fuel tank capacity | 45 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| CarChack co.uk | page 11/11 |

CarCheck.co.uk page 11/11

| Number of axles | 2 |
|-----------------|------------|
| Engine number | DAJB035483 |