



report date: 2024-03-29

General information

Make	VOLVO
Model	S80 D DRIVE R-DESIGN
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 3

Date	2021-12-04
Pictures	59
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 2



Date	2021-12-04
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-06-26
Pictures	20
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-26
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	25
Total items failed	4

MOT #14	2023-09-08 15:59
MOT test number	774188024816
Result	✓ Passed
Next expiry date	2024-09-26
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #13	2023-09-08 09:54
MOT test number	760994718830
Result	✗ Failed
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
Fail	Front Service brake imbalanced across an axle (1.2.1 (b) (i))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #12	2022-09-13 10:43
MOT test number	481843120593
Result	✓ Passed

MOT #11	2021-09-27 09:20
MOT test number	673336064956
Result	✓ Passed

**MOT #10** 2020-03-31 10:11**MOT test number** 415658213364**Result** ✓ Passed**Advice** Fluid leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush (5.3.4 (a) (i))**MOT #9** 2020-03-31 08:36**MOT test number** 367306185650**Result** ✗ Failed**Fail** Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Fluid leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush (5.3.4 (a) (i))**MOT #8** 2019-04-09 08:04**MOT test number** 890271216608**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge wear (5.2.3 (e))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #7** 2018-04-20 07:55**MOT test number** 217991665363**Result** ✓ Passed**Advice** Oil leak



<b>MOT #6</b>	2017-04-12 14:04
<b>MOT test number</b>	601464703012
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak

<b>MOT #5</b>	2016-04-09 08:13
<b>MOT test number</b>	752134446433
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)

<b>MOT #4</b>	2015-04-10 08:54
<b>MOT test number</b>	917470505125
<b>Result</b>	✓ Passed
<b>Notice</b>	Under-trays fitted obscuring some underside components

<b>MOT #3</b>	2014-04-17 09:18
<b>MOT test number</b>	699347904173
<b>Result</b>	✓ Passed
<b>Notice</b>	Under-trays fitted obscuring some underside components
<b>Notice</b>	Items removed from driver's view prior to test
<b>Notice</b>	Engine covers fitted obscuring some components in the engine bay

**MOT #2** 2013-04-18 11:43**MOT test number** 279048103460**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Items removed from driver's view prior to test
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Vehicle's internal headlight adjuster altered to recheck lights

**MOT #1** 2013-04-18 11:43**MOT test number** 839358503129**Result** ✗ Failed

- Pass with rectification** Offside Headlamp aim too low (1.8)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Items removed from driver's view prior to test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
26 September 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	26 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-27
Last registration	2023-09-08
Complete history	<a href="#">See info</a>



Registration #1	2010-04-27	20 mi
Registration #2	2013-04-18	17.320 mi
Registration #3	2014-04-17	21.918 mi
Registration #4	2015-04-10	28.212 mi
Registration #5	2016-04-09	33.601 mi
Registration #6	2017-04-12	40.338 mi
Registration #7	2018-04-20	48.073 mi
Registration #8	2019-04-09	56.408 mi
Registration #9	2020-03-31	64.325 mi
Registration #10	2020-05-20	70.377 mi
Registration #11	2020-05-20	70.377 mi
Registration #12	2020-05-20	70.377 mi
Registration #13	2020-05-20	70.377 mi
Registration #14	2020-05-20	70.377 mi
Registration #15	2020-05-20	70.377 mi
Registration #16	2020-05-20	70.377 mi
Registration #17	2020-05-20	70.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	957553