



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D DRIVE R-DESIGN
Colour	Blue
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-06-30
Pictures	10
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-21
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	21
Total items failed	22

MOT #19	2023-11-22 13:06
MOT test number	777819708909
Result	✓ Passed
Next expiry date	2024-11-21
Advice	Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Minor	Offside Front Headlamp lens slightly defective lens has condensation (4.1.1 (b) (i))
Advice	Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #18**

2023-11-15 10:40

**MOT test number**

777365867996

**Result**

✗ Failed

- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm 225/45/17 (5.2.3 (e))
- Fail** Offside Rear Inner Tyre has ply or cords exposed 225/45/17 (5.2.3 (d) (ii))
- Minor** Offside Front Headlamp lens slightly defective lens has condensation (4.1.1 (b) (i))
- Fail** Nearside Rear Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))
- Fail** Nearside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- Fail** Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 225/45/17 (5.2.3 (e))
- Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Offside Rear Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))

**MOT #17**

2022-11-18 12:42

**MOT test number**

152776624200

**Result**

✓ Passed

- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #16**

2022-02-25 15:31

**MOT test number**

776697407360

**Result**

✓ Passed

**MOT #15** 2022-02-25 15:05**MOT test number** 119780988700**Result** ✗ Failed**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**MOT #14** 2021-02-22 12:46**MOT test number** 220995406508**Result** ✓ Passed**MOT #13** 2019-07-03 11:15**MOT test number** 605392247295**Result** ✓ Passed**MOT #12** 2019-07-01 14:01**MOT test number** 178673407616**Result** ✗ Failed**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Headlamp aim too low and too far to the left. (4.1.2 (a))**MOT #11** 2018-06-28 15:09**MOT test number** 631681889989**Result** ✓ Passed

**MOT #10**

2018-06-28 09:42

**MOT test number**

798198006721

**Result****✗ Failed**

- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Rear Direction indicator slightly discoloured both (4.4.3 (a))

**MOT #9**

2017-10-24 15:10

**MOT test number**

322436967855

**Result****✓ Passed**

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

**MOT #8**

2017-10-24 10:04

**MOT test number**

681819022638

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)
- Fail** Offside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)
- Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)
- Fail** Nearside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #7** 2016-10-20 15:41**MOT test number** 780063341426**Result** ✓ Passed

- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Wishbone (2.4.G.2)
- Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Wishbone (2.4.G.2)

**MOT #6** 2015-10-26 12:17**MOT test number** 404737066034**Result** ✓ Passed**MOT #5** 2015-10-23 10:42**MOT test number** 304306599133**Result** ✗ Failed

- Fail** Nearside Steering rack gaiter insecure (2.2.D.2d)

**MOT #4** 2014-10-07 14:27**MOT test number** 847450884206**Result** ✓ Passed**MOT #3** 2014-10-07 10:19**MOT test number** 106870484213**Result** ✗ Failed

- Fail** Nearside Steering arm has relative movement at its fixings (2.2.B.1h)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #2	2013-10-23 10:28
MOT test number	508916093212
Result	✓ Passed
MOT #1	2012-10-29 12:22
MOT test number	479873902304
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
21 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	21 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DE59XYT
Plate since	2019-03-28
Current registration	DE59XYT
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-10-28
Last registration	2023-11-22
Complete history	<a href="#">See info</a>



Registration #1	2009-10-28	29 mi
Registration #2	2012-10-29	32.449 mi
Registration #3	2013-10-23	38.441 mi
Registration #4	2014-10-07	49.077 mi
Registration #5	2014-10-07	49.077 mi
Registration #6	2015-10-23	64.156 mi
Registration #7	2015-10-26	64.166 mi
Registration #8	2016-10-20	75.281 mi
Registration #9	2017-10-24	88.312 mi
Registration #10	2017-10-24	88.312 mi
Registration #11	2018-06-28	93.306 mi
Registration #12	2019-06-28	93.317 mi
Registration #13	2019-06-28	93.317 mi
Registration #14	2019-06-28	93.317 mi
Registration #15	2019-06-28	93.317 mi
Registration #16	2019-06-28	93.317 mi
Registration #17	2019-06-28	93.317 mi
Registration #18	2019-06-28	93.317 mi
Registration #19	2019-06-28	93.317 mi
Registration #20	2019-06-28	93.317 mi
Registration #21	2019-06-28	93.317 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	704037