



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2006
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	42.2 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-06-23
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-06-02
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	23
Total items failed	6

MOT #17 2023-06-03 07:24**MOT test number** 247939974077**Result** Passed**Next expiry date** 2024-06-02**Advice** Nearside Brake pipe corroded, covered in grease or other material Front to Rear (1.1.11 (c))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Nearside and Offside (5.3.4 (a) (i))**MOT #16** 2022-05-26 09:38**MOT test number** 419864748108**Result** Passed**MOT #15** 2022-05-20 11:43**MOT test number** 303177657421**Result** Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

**MOT #14** 2021-06-02 09:56**MOT test number** 608718540441**Result** ✓ Passed**MOT #13** 2020-03-21 10:37**MOT test number** 488705056423**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2019-03-16 09:58**MOT test number** 777502952150**Result** ✓ Passed**Advice** Nearside Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #11** 2018-04-03 11:41**MOT test number** 477790631147**Result** ✓ Passed**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2018-04-03 08:57**MOT test number** 565924960873**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)**MOT #9** 2017-03-31 09:07**MOT test number** 100110813647**Result** ✓ Passed**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #8** 2016-02-20 10:01**MOT test number** 632387593842**Result** ✓ Passed**MOT #7** 2015-02-20 10:30**MOT test number** 649131055000**Result** ✓ Passed**MOT #6** 2014-02-15 11:01**MOT test number** 717096944069**Result** ✓ Passed

**MOT #5** 2013-02-20 11:58**MOT test number** 265671853047**Result** ✓ Passed

- Advice** Inner Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2012-02-22 16:52**MOT test number** 426933852066**Result** ✓ Passed

- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Oil leak
- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)
- Notice** Wheel arches full of mud

MOT #3 2011-02-14 09:20**MOT test number** 189365441474**Result** ✓ Passed

- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)

MOT #2 2010-02-27 14:56**MOT test number** 234738350009**Result** ✓ Passed



MOT #1	2009-02-28 10:01
MOT test number	152089759055
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
2 June 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	2 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 WJ06BXV
Plate since	2019-06-29
Current registration	 WJ06BXV
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-03-01
Last registration	2023-06-03
Complete history	See info



Registration #1	2006-03-01	10 mi
Registration #2	2009-02-28	27.505 mi
Registration #3	2010-02-27	44.096 mi
Registration #4	2011-02-14	56.212 mi
Registration #5	2012-02-22	64.813 mi
Registration #6	2013-02-20	71.434 mi
Registration #7	2014-02-15	76.886 mi
Registration #8	2015-02-20	82.482 mi
Registration #9	2016-02-20	88.654 mi
Registration #10	2017-02-20	95.000 mi
Registration #11	2018-02-20	101.000 mi
Registration #12	2019-02-20	107.000 mi
Registration #13	2020-02-20	113.000 mi
Registration #14	2021-02-20	119.000 mi
Registration #15	2022-02-20	125.000 mi
Registration #16	2023-02-20	131.000 mi
Registration #17	2024-02-20	137.000 mi
Registration #18	2025-02-20	143.000 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430743161