





General information

| Make | KIA |
|---------------------|-------------------|
| Model | VENGA 4 |
| Colour | Red |
| Year of manufacture | 2017 |
| Top speed | 112 mph |
| 0 - 60 mph | 11.1 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 123 BHP |
|-------------------------|---------------------|
| Max. torque | 156 Nm at 4.200 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 32.8 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 43.5 mpg |
| CO2 emission | 150 g/km |
| CO2 label | F |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-06-10 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| MOT expiry date | 2025-03-29 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 5 |
| Failed MOT tests | 0 |
| Total advice items | 11 |
| Total items failed | 0 |

| MOT #5 | | 2024-03-25 17:08 |
|-----------|---|------------------|
| MOT test | number | 172131861129 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-03-29 |
| Advice | Nearside Front tyre badly worn on inner shoulder | |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Front tyre badly worn on inner shoulder | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #4 | | 2023-03-28 12:47 |
|----------|---|------------------|
| MOT test | number | 521394568038 |
| Result | | ✓ Passed |
| Advice | Nearside Front tyre worn on inner edge | |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Offside Front tyre worn on inner edge | |





| MOT #3 | 2022-03-25 10:28 |
|---|------------------|
| MOT test number | 680190516464 |
| Result | ✓ Passed |
| Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt | |
| MOT #2 | 2021-03-30 10:23 |
| MOT test number | 372210556140 |
| Result | 🗸 Passed |
| | |
| MOT #1 | 2020-03-25 17:28 |
| MOT test number | 913967039368 |
| Result | ✓ Passed |
| Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i) |) |



WF17ULA report date: 2024-03-28

Tax & MOT check

| ✓ Taxed | ✓ MOT |
|---------------------------|---|
| 1 June 2024 Tax status | Expires: 29 March 2025 Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 29 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | FEIDO |
| Category | 4. ARMPE |
| Туре | |
| Damage 2 | AMPL |
| | F Stores |
| Date | 1.E |
| Category | ante |
| Туре | |

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second s | |
|---|-------------|
| ********** | |
| ****** | |
| ****** | |
| ********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| | |
| Current registration | |
| Carrent registration Plate since | |





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2017-03-30 |
| Last registration | 2024-03-25 |
| Complete history | See info |



| Registration #1 | 2017-03-30 | 14 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-03-25 | 5.291 mi |
| Registration #3 | 2021-03-30 | 5.587 mi |
| Registration #4 | | 11.117 esi |
| Registration #5 | | 11.177 mi |
| Registration #6 | | 11.117 esi |
| Registration #7 | | 11.777 esi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 85% |
| Pedestrian | 64% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1765 mm |
| Height | 1600 mm |
| Length | 4075 mm |
| Wheel base | 2615 mm |
| Kerb weight | 1410 kg |
| Max. allowed weight | 1780 kg |
| Additional information | |
| Fuel tank capacity | 50 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|--------------|
| Engine number | G4FCHZ842122 |