



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV4 VVT-I XT4
Colour	Blue
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-05-26
Pictures	25
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2023-06-23
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	47
Total items failed	34

MOT #22 2022-06-01 14:21

MOT test number 853389010788

Result ✓ Passed

Next expiry date 2023-06-23

**Minor** Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both (2.1.3 (g) (i))

**Minor** Front Suspension arm ball joint dust cover severely deteriorated both (5.3.4 (b) (i))

**Advice** Underbody seal heavily used

**Advice** Nearside Front Nail in tyre

MOT #21 2022-06-01 10:26

MOT test number 911391073839

Result ✗ Failed

**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**Advice** Nearside Front Nail in tyre

**Minor** Front Suspension arm ball joint dust cover severely deteriorated both (5.3.4 (b) (i))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Advice** Underbody seal heavily used

**Fail** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

**Minor** Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both (2.1.3 (g) (i))

**MOT #20** 2021-06-24 07:50**MOT test number** 193190735859**Result** ✓ Passed**MOT #19** 2020-10-12 10:45**MOT test number** 125022544179**Result** ✓ Passed**MOT #18** 2019-10-14 14:50**MOT test number** 246851962564**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #17** 2019-10-14 09:40**MOT test number** 903892031364**Result** ✗ Failed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Front Service brake excessively binding nearside and offside (1.2.1 (f))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #16** 2018-10-15 15:22**MOT test number** 889634485704**Result** ✓ Passed**Advice** Nearside front tyre perished

**MOT #15** 2018-10-15 13:45**MOT test number** 503187998707**Result** ✗ Failed**Fail** Nearside Position lamp not working (4.2.1 (a))**Advice** Nearside front tyre perished**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #14** 2017-10-19 15:58**MOT test number** 470552198421**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (3.5.1i)**MOT #13** 2017-10-19 12:25**MOT test number** 205842140471**Result** ✗ Failed**Fail** Front registration plate letter/figure missing (6.3.1c)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (3.5.1i)**Fail** Tyre has a cut in excess of the requirements deep enough to reach the ply or cords offside rear tyre perished and split to excess (4.1.D.1a)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Direction indicator incorrect colour giving off white light (1.4.A.2f)

**MOT #12**

2015-11-26 09:51

**MOT test number**

222857705794

**Result**

✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Exhaust emmisions not carried out due to exhaust leak
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Offside Rear slight slit on tyre wall not showing canvas

**MOT #11**

2015-11-23 15:26

**MOT test number**

267430785493

**Result**

✗ Failed

- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Advice** Exhaust emmisions not carried out due to exhaust leak
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Fail** Front Exhaust has a major leak of exhaust gases at cat (7.1.2)
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Advice** Offside Rear slight slit on tyre wall not showing canvas
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Fail** Nearside Rear Stop lamp not working (1.2.1b)

**MOT #10** 2014-04-30 17:32**MOT test number** 276590924488**Result** ✓ Passed**MOT #9** 2014-04-30 09:41**MOT test number** 218340924496**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #8** 2012-12-21 17:51**MOT test number** 256056852300**Result** ✓ Passed**Advice** Offside Brake pipe slightly corroded (3.6.B.2c)**Notice** P/s fluid levle on min**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**Notice** Unable to access rear seats or seat belts (dog cage in back)**Notice** Cat heat shield loose**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2012-12-21 11:47**MOT test number** 547446552329**Result** ✗ Failed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear coil spring cracked (2.4.C.1a)**Notice** Unable to access rear seats or seat belts (dog cage in back)**Advice** Offside Brake pipe slightly corroded (3.6.B.2c)**Notice** Cat heat shield loose**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**Notice** P/s fluid levle on min**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2011-11-25 12:11**MOT test number** 448639821409**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)



**MOT #5** 2010-11-19 12:37**MOT test number** 624123720359**Result** ✓ Passed**MOT #4** 2010-11-19 12:30**MOT test number** 843863820330**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2009-11-20 11:59**MOT test number** 813904629336**Result** ✓ Passed**MOT #2** 2009-11-20 11:01**MOT test number** 954544229329**Result** ✗ Failed**Fail** Rear registration plate background overprinted or shadowed with text (6.3.1e)**Fail** Front registration plate background overprinted or shadowed with text (6.3.1e)**MOT #1** 2008-11-06 15:57**MOT test number** 813861218303**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-11-22
Last registration	2022-06-01
Complete history	<a href="#">See info</a>



Registration #1	2005-11-22	14 mi
Registration #2	2008-11-06	22.910 mi
Registration #3	2009-11-20	30.324 mi
Registration #4	2009-11-20	30.324 mi
Registration #5	2010-11-19	37.465 mi
Registration #6	2010-11-19	37.465 mi
Registration #7	2011-11-25	47.850 mi
Registration #8	2012-12-21	55.003 mi
Registration #9	2012-12-21	55.003 mi
Registration #10	2014-04-30	61.344 mi
Registration #11	2014-04-30	61.344 mi
Registration #12	2015-11-23	69.036 mi
Registration #13	2016-06-01	75.000 mi
Registration #14	2016-06-01	75.000 mi
Registration #15	2016-06-01	75.000 mi
Registration #16	2016-06-01	75.000 mi
Registration #17	2016-06-01	75.000 mi
Registration #18	2016-06-01	75.000 mi
Registration #19	2016-06-01	75.000 mi
Registration #20	2016-06-01	75.000 mi
Registration #21	2016-06-01	75.000 mi
Registration #22	2016-06-01	75.000 mi
Registration #23	2016-06-01	75.000 mi
Registration #24	2016-06-01	75.000 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1AZ1653805