



HYUNDAI



report date: 2024-03-28

General information

| | |
|---------------------|------------------|
| Make | HYUNDAI |
| Model | I30 CRDI COMFORT |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 117 mph |
| 0 - 60 mph | 11.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 113 BHP |
| Max. torque | 260 Nm at 1.900 rpm |
| Engine capacity | 1.582 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 124 g/km |
| CO2 label | D |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-04 |
| Pictures | 1 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-04 |
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 18 |
| Total items failed | 9 |

| | |
|------------------|--|
| MOT #13 | 2023-05-18 15:46 |
| MOT test number | 648319184868 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-04 |
| Advice | Offside Front Play in steering rack inner joint(s) |

| | |
|-----------------|---|
| MOT #12 | 2023-05-11 13:45 |
| MOT test number | 186310641165 |
| Result | ✗ Failed |
| Advice | Offside Front Service brake binding but not excessively (1.2.1 (f)) |
| Advice | Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) |
| Fail | Offside Front Service brake excessively fluctuating (1.2.1 (e)) |
| Advice | Offside Rear Service brake binding but not excessively (1.2.1 (f)) |
| Fail | Nearside Side repeater not working (4.4.1 (a) (ii)) |

**MOT #11** 2022-05-05 14:05**MOT test number** 492482798805**Result** ✓ Passed**Advice** Offside Front Tyre worn on inner edge**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Front (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front (5.3.4 (a) (i))**Advice** Offside rear and nearside front tyres wearing on edges**MOT #10** 2021-06-05 09:56**MOT test number** 729083101113**Result** ✓ Passed**MOT #9** 2020-09-22 10:40**MOT test number** 131986228743**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #8** 2019-10-02 10:23**MOT test number** 298786027908**Result** ✓ Passed

**MOT #7** 2019-09-26 08:08**MOT test number** 413299365523**Result** ✗ Failed**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside front tyre worn on inner edge**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2018-11-24 09:24**MOT test number** 202638676053**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2017-12-01 11:57**MOT test number** 100431374403**Result** ✓ Passed**MOT #4** 2016-11-28 14:25**MOT test number** 903665327287**Result** ✓ Passed



| | |
|-----------------|--|
| MOT #3 | 2016-11-28 10:18 |
| MOT test number | 381874406157 |
| Result | ✗ Failed |
| Fail | Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i) |
| Fail | Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i) |
| Fail | Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i) |
| Fail | Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i) |

| | |
|-----------------|------------------|
| MOT #2 | 2015-11-28 09:07 |
| MOT test number | 728866458901 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #1 | 2014-11-28 11:37 |
| MOT test number | 707242734336 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
4 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 4 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2020-01-01 |
| Current registration | XXXXXX |
| Plate since | 2020-01-01 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2011-12-01 |
| Last registration | 2023-05-18 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-12-01 | 26 mi |
| Registration #2 | 2014-11-28 | 21.426 mi |
| Registration #3 | 2015-11-28 | 35.384 mi |
| Registration #4 | 2016-11-28 | 47.329 mi |
| Registration #5 | 2016-11-28 | 47.329 mi |
| Registration #6 | 2017-12-01 | 59.973 mi |
| Registration #7 | 2018-11-24 | 71.119 mi |
| Registration #8 | 2019-09-26 | 78.497 mi |
| Registration #9 | 2020-05-20 | 85.377 mi |
| Registration #10 | 2020-05-20 | 85.377 mi |
| Registration #11 | 2020-05-20 | 85.377 mi |
| Registration #12 | 2020-05-20 | 85.377 mi |
| Registration #13 | 2020-05-20 | 85.377 mi |
| Registration #14 | 2020-05-20 | 85.377 mi |
| Registration #15 | 2020-05-20 | 85.377 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1775 mm |
| Height | 1565 mm |
| Length | 4475 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1442 kg |
| Max. allowed weight | 1920 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 53 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|--------------|
| Number of axles | 2 |
| Engine number | D4FBBZ335254 |