



HYUNDAI

UK **HJ55ZHC**


report date: 2024-10-06

General information

Make	HYUNDAI
Model	SONATA CDX
Colour	Grey
Year of manufacture	2005
Top speed	126 mph
0 - 60 mph	10.4 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	160 BHP
Max. torque	219 Nm at 4.250 rpm
Engine capacity	2.359 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.0 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.1 mpg
CO2 emission	210 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-13
Pictures	41
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-09-23
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	46
Total items failed	6

MOT #20 2024-09-12 14:43

MOT test number 138749542696

Result ✔ Passed

Next expiry date 2025-09-23

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Rear Inner Sill Corroded but not excessive
- Advice** Fuel Pipe/s corroded



MOT #19 2023-09-09 13:04

MOT test number 578320522354

Result ✔ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #18 2022-09-24 12:40

MOT test number 175497420553

Result ✔ Passed

- Advice** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #17 2021-09-17 08:58

MOT test number 956761348489

Result ✔ Passed

- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))



MOT #16 2021-09-17 08:58

MOT test number 909415567109

Result ✗ Failed

Pass with rectification Front Windscreen wiper blade missing (3.4 (b) (ii))

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #15 2020-10-21 11:30

MOT test number 454834858274

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2019-10-23 10:39

MOT test number 832351423500

Result ✓ Passed

Advice Play in steering rack inner joint(s)

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #13 2018-10-24 08:32

MOT test number 147860454470

Result ✓ Passed



MOT #12 2017-10-20 16:04

MOT test number 692512797888

Result ✓ Passed

- Advice** Rear registration plate faded but not likely to be misread (6.3.1d)
- Advice** Sill covers fitted

MOT #11 2017-05-15 09:17

MOT test number 520064351172

Result ✓ Passed

- Advice** Under cover fitted obscuring some testable components.
- Advice** Surface corrosion to exhaust system.
- Advice** Both front tyres wearing on inner & outer edges.

MOT #10 2017-05-12 14:54

MOT test number 231824217176

Result ✗ Failed

- Advice** Both front tyres wearing on inner & outer edges.
- Fail** Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)
- Advice** Under cover fitted obscuring some testable components.
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Surface corrosion to exhaust system.
- Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #9 2016-04-21 12:19

MOT test number 854248975222

Result ✓ Passed

- Advice** Under cover fitted



MOT #8 2015-04-21 15:33

MOT test number 386531515135

Result ✓ Passed

Notice Vehicle's internal headlight adjuster altered to recheck lights

Notice Engine covers fitted obscuring some components in the engine bay

Notice Surface corrosion to exhaust system

Notice Under-trays fitted obscuring some underside components

Notice Both front tyres wearing on outer edges

MOT #7 2014-04-17 16:35

MOT test number 106477004171

Result ✓ Passed

Notice Sill covers fitted

Notice Slight play in nearside steering rack arm

MOT #6 2013-04-05 15:47

MOT test number 756445793046

Result ✓ Passed

Notice Both rear tyres perished and wearing low on edges

MOT #5 2012-04-18 10:59

MOT test number 409689002101

Result ✓ Passed

MOT #4 2011-05-03 13:01

MOT test number 408873121107

Result ✓ Passed



MOT #3	2011-05-03 12:55
MOT test number	375743221170
Result	✗ Failed
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2	2009-09-14 16:41
MOT test number	641787359275
Result	✓ Passed

MOT #1	2008-09-02 11:14
MOT test number	304386148427
Result	✓ Passed
Notice	All four tyres perished/cracked



Tax & MOT check

✓
Taxed

Tax due:
1 October 2025

✓
MOT

Expires:
23 September 2025

Tax status Valid until 1 October

Days left 326

MOT expiry date 23 September 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-09-29
Current registration	XXXXXX
Plate since	2024-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-29
Last registration	2024-09-12
Complete history	See info



Registration #1	2005-09-29	14 mi
Registration #2	2008-09-02	8.342 mi
Registration #3	2009-09-14	11.416 mi
Registration #4	2011-05-03	16.543 mi
Registration #5	2011-05-03	16.543 mi
Registration #6	2012-04-18	21.837 mi
Registration #7	2013-04-05	25.856 mi
Registration #8	2014-04-17	29.184 mi
Registration #9	2015-04-21	32.701 mi
Registration #10	2016-04-21	35.517 mi
Registration #11	2017-05-12	35.544 mi
Registration #12	2018-05-29	35.577 mi
Registration #13	2019-05-29	35.577 mi
Registration #14	2020-05-29	35.577 mi
Registration #15	2021-05-29	35.577 mi
Registration #16	2022-05-29	35.577 mi
Registration #17	2023-05-29	35.577 mi
Registration #18	2024-05-29	35.577 mi
Registration #19	2024-05-29	35.577 mi
Registration #20	2024-05-29	35.577 mi
Registration #21	2024-05-29	35.577 mi
Registration #22	2024-05-29	35.577 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1832 mm
Height	1475 mm
Length	4800 mm
Wheel base	2730 mm
Kerb weight	1546 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	G4KC5094077