



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SCIROCCO GT TDI
Colour	Blue
Year of manufacture	2009
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





## MOT history

MOT expiry date	2021-02-25
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	23
Total items failed	7

MOT #14	2020-02-26 11:28
MOT test number	582606743395
Result	✓ Passed
Next expiry date	2021-02-25

MOT #13	2019-02-13 09:29
MOT test number	358603158715
Result	✓ Passed
Advice	Handbrake just passable -feels stiff -osr caliper not going fully back
Advice	Nearside Front suspension lever broken -not self levelling
Advice	Center exhaust sleeve corroded away---- not loose

MOT #12	2018-01-30 12:07
MOT test number	668791550753
Result	✓ Passed

**MOT #11** 2017-03-09 10:12**MOT test number** 333210444859**Result** ✓ Passed**Advice** Nearside outer sill damaged**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Sidewall of nearside rear tyre starting to split**MOT #10** 2016-03-15 17:19**MOT test number** 161889680461**Result** ✓ Passed**Advice** Engine covers fitted**Advice** Undertrays fitted**MOT #9** 2015-02-21 08:40**MOT test number** 648312155063**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #8** 2015-02-20 13:55**MOT test number** 487761255043**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Passenger door cannot be opened from outside the vehicle (6.2.B.1c)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #7** 2014-05-24 14:31**MOT test number** 995624844106**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2014-01-09 10:03**MOT test number** 208899904085**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2014-01-09 10:03**MOT test number** 768959504027**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2013-01-10 10:16**MOT test number** 586240613083**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-01-10 10:16**MOT test number** 926280313084**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) incorrect colour (1.1.A.3e)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-01-23 09:26**MOT test number** 668853722012**Result** ✓ Passed**MOT #1** 2012-01-23 09:26**MOT test number** 198553122042**Result** ✗ Failed**Pass with rectification** Headlamp aim too low (1.8)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>SW58CLF</b>
Plate since	2019-06-29
Current registration	 <b>SW58CLF</b>
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-01-23
Last registration	2020-02-26
Complete history	<a href="#">See info</a>



Registration #1	2009-01-23	9 mi
Registration #2	2012-01-23	21.826 mi
Registration #3	2013-01-10	34.771 mi
Registration #4	2014-01-09	53.468 mi
Registration #5	2014-05-24	57.658 mi
Registration #6	2015-02-20	71.095 mi
Registration #7	2015-05-20	75.277 mi
Registration #8	2015-05-20	75.277 mi
Registration #9	2015-05-20	75.277 mi
Registration #10	2015-05-20	75.277 mi
Registration #11	2015-05-20	75.277 mi
Registration #12	2015-05-20	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CBD 437987