



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 300 SWB LR P/V 110
Colour	Blue
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	300 Nm at 2.250 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.2 mpg







LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-18
Pictures	13
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-13
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	55
Total items failed	1

MOT #14	2023-10-14 13:07
MOT test number	531546864068
Result	✓ Passed
Next expiry date	2024-10-13
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Brake pipe corroded, covered in grease or other material two, front to rear pipes (1.1.11 (c))

MOT #13	2022-08-05 10:33
MOT test number	671830870864
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear lens damaged but noy showing any white light

**MOT #12**

2022-08-03 08:57

MOT test number

285839768624

Result**✗ Failed****MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear lens damaged but not showing any white light**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #11**

2021-07-26 16:54

MOT test number

674020596513

Result**✓ Passed****Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Top brake lamp not working**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Central Brake pipe corroded, covered in grease or other material both (1.1.11 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #10

2021-07-08 09:39

MOT test number

193943676943

Result

✗ Failed

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Inner Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Central Brake pipe corroded, covered in grease or other material nearside pipe marked yellow (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Top brake lamp not working**DANGEROUS** Nearside Front Suspension arm pin or bush likely to become detached rear bush (5.3.4 (a) (ii))**MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material marked yellow (1.1.11 (c))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #9

2020-07-09 08:42

MOT test number

504119024808

Result

✓ Passed

**MOT #8** 2019-06-18 08:21**MOT test number** 118925894715**Result** ✓ Passed**MOT #7** 2019-06-17 11:39**MOT test number** 376731374094**Result** ✗ Failed

MAJOR Exhaust emissions test aborted because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

MAJOR Offside Front Brake pipe excessively corroded (1.1.11 (c))

MAJOR Rear Brake disc significantly and obviously worn both (1.1.14 (a) (i))

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MAJOR Windscreen washer not working (3.5 (a))

MAJOR Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Central Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Front Brake disc significantly and obviously worn both (1.1.14 (a) (i))

MAJOR Front Registration plate inscription illegible (0.1 (b))

MAJOR Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MAJOR Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MAJOR Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

MOT #6 2018-06-25 09:04**MOT test number** 938370723680**Result** ✓ Passed

**MOT #5** 2017-06-30 13:18**MOT test number** 641046860991**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Anti-roll bar has slight play in a ball joint both front (2.4.G.2)**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement both front (rear) (2.4.G.2)**MOT #4** 2016-07-20 14:02**MOT test number** 753890849425**Result** ✓ Passed**MOT #3** 2015-07-03 07:41**MOT test number** 489524785127**Result** ✓ Passed**MOT #2** 2015-06-26 11:20**MOT test number** 336527175133**Result** ✗ Failed**Fail** Nearside Front wheel bearing rough when rotated (2.5.A.2)**MOT #1** 2014-06-23 13:56**MOT test number** 795684474169**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
13 October 2024

Tax status		Valid until 1 June
Days left		32
MOT expiry date		13 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 SW11EXR
Plate since	2024-03-28
Current registration	 SW11EXR
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-07-21
Last registration	2023-10-14
Complete history	See info



Registration #1	2011-07-21	8 mi
Registration #2	2014-06-23	22.778 mi
Registration #3	2015-06-26	31.297 mi
Registration #4	2015-07-03	31.525 mi
Registration #5	2016-07-20	41.062 mi
Registration #6	2017-06-30	53.517 mi
Registration #7	2018-06-25	66.096 mi
Registration #8	2019-06-17	76.033 mi
Registration #9	2020-06-20	86.070 mi
Registration #10	2021-06-23	96.107 mi
Registration #11	2022-06-26	106.144 mi
Registration #12	2023-06-29	116.181 mi
Registration #13	2024-06-30	126.218 mi
Registration #14	2025-06-30	136.255 mi
Registration #15	2026-06-30	146.292 mi
Registration #16	2027-06-30	156.329 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2374 mm
Height	2077 mm
Length	4863 mm
Kerb weight	1680 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	BY11241