





report date: 2024-03-28

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Red
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 104 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2021-11-10

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

 Date
 2021-11-09

 Pictures
 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



CU63NKR report date: 2024-03-28

MOT history

MOT expiry date	2024-05-17
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	15
Total items failed	4

MOT #14	2023-05-18 13:17
MOT test number	606603678875
Result	✓ Passed
Next expiry date	2024-05-17

MOT #13	2022-06-23 05:21
MOT test number	724584334136
Result	✓ Passed

MOT #12		2021-11-05 13:03
MOT test	number	723475940564
Result		✓ Passed
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))	

MOT #11		2020-11-25 16:05
MOT test	number	701847315493
Result		✓ Passed
Advice	Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10 2020-11-25 09:30

MOT test number 253745426060

Result X Failed

Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

Fail Offside Front Brake hose leaking on a hydraulic braking system (1.1.12 (c) (ii))

MOT #9 2019-11-19 13:11

MOT test number 214737479257

Result \square Passed

Advice Nearside Front Nail in tyre

MOT #8 2018-11-22 12:04

MOT test number 328569534740

Result ✓ Passed

MOT #7 2018-11-19 15:44

MOT test number 968523781551

Result X Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2018-07-24 12:56

MOT test number 410407135276

Result ✓ Passed

MOT #5 2018-07-24 12:56

MOT test number 803011069761

Result X Failed

Pass with rectification Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4

MOT test number

855901833730

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2016-11-18 15:45

MOT test number 536428922214

MOT #2 2016-06-21 14:03

MOT test number 149874863738

Result \(\sqrt{Passed} \)

Advice Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Offside Front Tyre worn close to the legal limit 1.9mm (4.1.E.1)

MOT #1 2016-06-21 13:41

MOT test number 934916199429

Result X Failed

Advice Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

Advice Offside Front Tyre worn close to the legal limit 1.9mm (4.1.E.1)

Advice Vehicles internal headlight adjuster altered to recheck lights

Fail Offside Stop lamp not working (1.2.1b)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	17 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



CU63NKR report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
PROPERTY.	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	AIR.
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



CU63NKR report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-09-04
Last registration	2023-05-18
Complete history	See info



Registration #1	2013-09-04	8 mi
Registration #2	2016-06-21	22.100 mi
Registration #3	2016-06-21	22.100 mi
Registration #4	2016-11-18	26.040 mi
Registration #5	2017-10-24	28.464 mi
Registration #6	2018-07-24	29.671 mi
Registration #7	2018-07-24	29.671 mi
Registration #8	2018-11-19	29.799 mi
Registration #9	2018-11-22	29.799 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		9.377 66

More info >

CarCheck.co.uk page 11/12



CU63NKR report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1208 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

CT29076