



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 VVTI XT4
Colour	Grey
Year of manufacture	2007
Top speed	115 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	194 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	39.2 mpg
Consumption combined	32.8 mpg
CO2 emission	202 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-27
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-23
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	33
Total items failed	4

MOT #16 2023-10-14 12:18

MOT test number 356592245645

Result ✓ Passed

Next expiry date 2024-10-23

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Inner Inner tie rod has slight play
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15 2022-10-19 16:20

MOT test number 767912163787

Result ✓ Passed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Coil spring corroded both sides (5.3.1 (b) (i))

**MOT #14**

2022-10-19 16:20

MOT test number

881696972226

Result

✗ Failed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Coil spring corroded both sides (5.3.1 (b) (i))**MOT #13**

2021-10-20 09:55

MOT test number

193840504079

Result

✓ Passed

Advice Underside off the vehicle corroded but not excessive.**MOT #12**

2020-10-13 09:46

MOT test number

371480822362

Result

✓ Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Central Rear Brake pipe corroded, covered in grease or other material @ rear n/s and o/s been greased (1.1.11 (c))**MOT #11**

2019-10-16 10:18

MOT test number

666049307355

Result

✓ Passed

Advice General underbody corrosion**Advice** Offside Front Brake disc worn, but not excessively Inner pad (1.1.14 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2018-10-22 11:51

MOT test number

281413141049

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear big bush (5.3.4 (a) (i))

Advice Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #9

2017-10-20 08:50

MOT test number

705265112926

Result

✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #8

2016-10-24 11:58

MOT test number

700434234881

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7

2015-09-02 15:12

MOT test number

296684985207

Result

✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

**MOT #6** 2014-09-05 14:39**MOT test number** 488838944251**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2013-09-05 12:27**MOT test number** 697528243295**Result** ✓ Passed**MOT #4** 2012-09-13 13:21**MOT test number** 338217952235**Result** ✓ Passed**MOT #3** 2012-09-12 11:09**MOT test number** 379116452484**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Anti-roll bar linkage fractured (2.4.G.1)**Notice** Frount discs heavelay corroded**Fail** Nearside Rear Anti-roll bar linkage fractured (2.4.G.1)**MOT #2** 2011-09-14 11:36**MOT test number** 189657051217**Result** ✓ Passed



MOT #1	2010-09-06 09:25
MOT test number	231329240213
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
23 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	23 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-10
Last registration	2023-10-14
Complete history	See info



Registration #1	2007-09-10	8 mi
Registration #2	2010-09-06	24.447 mi
Registration #3	2011-09-14	29.286 mi
Registration #4	2012-09-12	40.205 mi
Registration #5	2012-09-13	40.210 mi
Registration #6	2013-09-05	52.827 mi
Registration #7	2014-09-05	60.554 mi
Registration #8	2015-09-02	66.076 mi
Registration #9	2016-10-24	72.161 mi
Registration #10	2016-10-24	72.161 mi
Registration #11	2016-10-24	72.161 mi
Registration #12	2016-10-24	72.161 mi
Registration #13	2016-10-24	72.161 mi
Registration #14	2016-10-24	72.161 mi
Registration #15	2016-10-24	72.161 mi
Registration #16	2016-10-24	72.161 mi
Registration #17	2016-10-24	72.161 mi
Registration #18	2016-10-24	72.161 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1465 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1AZ5562494