





report date: 2024-03-28

## General information

Make	KIA
Model	RIO CRDI 1 AIR ECODYNAMICS
Colour	Silver
Year of manufacture	2012
Top speed	98 mph
0 - 60 mph	15.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	74 BHP
Max. torque	170 Nm at 1.500 rpm
Engine capacity	1.120 cc
Cylinders	3
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



# Internet history

#### Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-04
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	19
Total items failed	3

MOT #11		2023-08-02 10:05
MOT test	number	837360424249
Result		✓ Passed
Next exp	iry date	2024-08-04
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely de	teriorated (5.3.4 (b) (i))
Advice	Offside Front Brake/back/plate/deteriorated	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Exhaust/system/corroded	

MOT #10	2022-07-19 08:45
MOT test number	969734034902
Result	✓ Passed

CarCheck.co.uk page 3/12



**AX12GVA** 

report date: 2024-03-28

**MOT #9** 2021-07-20 14:13 **MOT** test number 732408307354 ✓ Passed Result **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) Minor **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT test number
946052540216

Result

Minor
Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice
Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice
Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice
Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7

MOT test number

825616458841

Result

✓ Passed

MOT #6

MOT test number

699179284496

Result

Advice Front discs lipped

Advice Slight corrosion on rear discs

CarCheck.co.uk page 4/12



**AX12GVA** 

report date: 2024-03-28

MOT #5	2017-07-19 14:11
MOT test number	594923420103
Result	✓ Passed
MOT #4	2016-07-22 13:59
MOT test number	454185362545
Result	✓ Passed
MOT #3	2016-07-22 11:20
MOT test number	903122121135
Result	<b>×</b> Failed
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #2		2015-07-30 11:33
MOT test	number	825581715208
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	

MOT #1		2015-07-30 11:33
MOT test	number	436831015256
Result		🗙 Failed
Notice Engine covers fitted obscuring some components in the engine bay		
Notice Under-trays fitted obscuring some underside components		
Pass wit	h rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)	

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	4 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Venicle class	43
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



# Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	
2000000	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	NIE UK
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-08-04
Last registration	2023-08-02
Complete history	See info



Registration #1	2012-08-04	16 mi
Registration #2	2015-07-30	42.589 mi
Registration #3	2016-07-22	55.981 mi
Registration #4	2016-07-22	55.981 mi
Registration #5	2017-07-19	68.152 mi
Registration #6	2018-07-24	80.830 mi
Registration #7		9.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.177 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1293 kg
Max. allowed weight	1640 kg

## Additional information

Fuel tank capacity	43 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12,

Number of axles 2

**Engine number** D3FACH312859