



General information

Make	VOLKSWAGEN
Model	TIGUAN SE TDI 4MOTION
Colour	Grey
Year of manufacture	2010
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-06
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-06-21
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	21
Total items failed	8

MOT #15	2023-06-22 08:04
MOT test number	109254369124
Result	✓ Passed
Next expiry date	2024-06-21
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #14	2022-02-09 16:53
MOT test number	699865491269
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement Both inner rear bushes (5.3.4 (a) (i))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both inner surfaces pitted (1.1.14 (a) (ii))
Advice	Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))

**MOT #13**

2022-02-09 15:08

MOT test number

275868616722

Result**✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both inner rear bushes (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both inner surfaces pitted (1.1.14 (a) (ii))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #12

2021-02-04 12:53

MOT test number

556200327163

Result**✓ Passed****MOT #11**

2021-02-03 09:32

MOT test number

544132623664

Result**✗ Failed**

- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))

MOT #10

2020-03-25 13:42

MOT test number

111484170368

Result**✓ Passed**

**MOT #9** 2020-03-20 15:22**MOT test number** 989085421965**Result** ✗ Failed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2019-04-09 13:23**MOT test number** 592279731496**Result** ✓ Passed**MOT #7** 2019-04-09 09:04**MOT test number** 496446360495**Result** ✗ Failed**Fail** Offside Rear Lower Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2018-04-16 09:39**MOT test number** 950089477894**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2017-04-05 08:11**MOT test number** 195554192854**Result** ✓ Passed



MOT #4	2016-04-06 11:25
MOT test number	370204983907
Result	✓ Passed
MOT #3	2015-04-10 11:08
MOT test number	338030805163
Result	✓ Passed
MOT #2	2014-04-18 10:50
MOT test number	237558604428
Result	✓ Passed
MOT #1	2013-04-11 09:49
MOT test number	908301103139
Result	✓ Passed
<div>Notice Emissions tested but too clean to record</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
21 June 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	VN10BNL
Plate since	2019-03-29
Current registration	VN10BNL
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-19
Last registration	2023-06-22
Complete history	See info



Registration #1	2010-04-19	26 mi
Registration #2	2013-04-11	18.108 mi
Registration #3	2014-04-18	22.224 mi
Registration #4	2015-04-10	25.916 mi
Registration #5	2016-04-06	30.755 mi
Registration #6	2017-04-05	39.836 mi
Registration #7	2018-04-16	47.939 mi
Registration #8	2019-04-09	55.029 mi
Registration #9	2019-04-09	55.029 mi
Registration #10	2020-04-09	62.119 mi
Registration #11	2021-04-09	69.209 mi
Registration #12	2022-04-09	76.299 mi
Registration #13	2023-04-09	83.389 mi
Registration #14	2024-04-09	90.479 mi
Registration #15	2025-04-09	97.569 mi
Registration #16	2026-04-09	104.659 mi
Registration #17	2027-04-09	111.749 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	79%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4427 mm
Wheel base	2604 mm
Kerb weight	1590 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBA 652186