





report date: 2024-03-29

General information

Make	FIAT
Model	DUCATO 35 LWB C/C MJ 120
Colour	White
Year of manufacture	2011
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.287 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2022-04-01

Pictures 25

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-02-26
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	7
Total items failed	22

MOT #15	2	2024-02-07 12:23
MOT test	number	724857160857
Result		✓ Passed
Next expi	ry date	2025-02-26
Advice	Front Registration plate deteriorated but not likely to be misread damaged (0.1 (b))

MOT #14	2023-02-27 16:23
MOT test number	776284418441
Result	✓ Passed
MOT #13	2022-06-23 12:50
MOT test number	712538385615
Result	✓ Passed
MOT #12	2021-06-23 09:43
MOT test number	515000253009
Result	✓ Passed

MOT #11	2020-06-16 09:02
MOT test number	888741247609
Result	✓ Passed

CarCheck.co.uk page 3/13



Fail

LD11ZGV

report date: 2024-03-29

	••	
MOT #	10	2019-06-25 16:13
MOT te	est number	648308116085
Result		✓ Passed
MOT #9	9	2019-06-20 09:19
MOT te	est number	938199579390
Result		🗙 Failed
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps	s (4.7.1 (b) (ii))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #8		2018-06-19 13:18
MOT test	number	572965160689
Result		✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakene	d (1.1.14 (a) (ii))
Advice	BOTH FRONT MIRROR COVERS BROKEN AND REPAIRED USING DUCK TAPE	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))		

Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

CarCheck.co.uk page 4/13



LD11ZGV

report date: 2024-03-29

MOT #7 2018-06-18 13:30 **MOT** test number 411613129763 Result **X** Failed Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a Fail wheel (1.3.1 (a) (i)) Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Service brake efficiency below requirements (1.2.2 (a) (i)) Fail Rear Service brake excessively fluctuating (1.2.1 (e)) Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 Fail (d)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6	2017-06-16 10:05
MOT test number	384324827210
Result	✓ Passed

MOT #5	2017-06-15 12:16
MOT test number	524812345325
Result	× Failed
Fail Exhaust emits an excessive level of metered smoke (7.4.B.3a)	

CarCheck.co.uk page 5/13



LD11ZGV

report date: 2024-03-29

MOT #	4	2016-06-09 16:20
MOT to	est number	509571352236
Result		✓ Passed
MOT #	3	2016-06-09 09:23
MOT to	est number	848641846753
Result		★ Failed
Fail	Headlamp not working on dipped beam Near side (1.7.5a)	
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Registration plate lamp not working Near side (1.1.C.1d)	

MOT #2	2015-06-11 15:43
MOT test number	516982965122
Result	✓ Passed
MOT #1	2014-05-22 11:09
MOT test number	466242044158
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Days left 125

MOT expiry date 26 February 2025

Full MOT history See MOT history

CarCheck.co.uk page 7/13




LD11ZGV

report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e union mestery		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I		?

	More info	>
Plate changes See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-05-23
Last registration	2024-02-07
Complete history	See info



Registration #1	2011-05-23	22 mi
Registration #2	2014-05-22	102.060 mi
Registration #3	2015-06-11	83.260 mi
Registration #4	2016-06-09	88.609 mi
Registration #5	2016-06-09	88.609 mi
Registration #6	2017-06-15	94.804 mi
Registration #7	2017-06-16	94.804 mi
Registration #8	2018-06-18	101.768 mi
Registration #9	2018-06-19	101.768 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.777 es

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	2350 mm
Height	2254 mm
Length	5943 mm

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	1450642

CarCheck.co.uk page 13/13