



report date: 2024-03-29

General information

Make	HONDA
Model	FR-V VTEC SPORT
Colour	Grey
Year of manufacture	2006
Top speed	120 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.6 mpg
CO2 emission	199 g/km
CO2 label	J





MOT history

MOT expiry date	2023-04-01
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	20
Total items failed	6

MOT #17 2022-04-02 07:21

MOT test number 315979509945

Result ✓ Passed

Next expiry date 2023-04-01

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #16 2021-03-02 11:04

MOT test number 712484631679

Result ✓ Passed

MOT #15 2020-03-03 15:50

MOT test number 400053186544

Result ✓ Passed

Advice Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Headlights fading due to age, still a beam pattern

MOT #14 2019-03-02 14:24

MOT test number 122281262662

Result ✓ Passed



MOT #13	2018-03-05 15:42
MOT test number	656643508573
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12	2018-02-19 12:35
MOT test number	995753547424
Result	✗ Failed
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Front engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)
Fail	Offside Front Power steering component(s) leaking resevoir (2.3.3b)
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Offside Rear Nail in tyre

MOT #11	2017-02-20 12:46
MOT test number	533921604528
Result	✓ Passed
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Front engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)

MOT #10	2016-02-08 10:22
MOT test number	538010548185
Result	✓ Passed
Advice	Front engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)
Advice	N/s wiper starting to split
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nail in o/s/r tyre

**MOT #9** 2015-02-09 10:17**MOT test number** 158220745048**Result** ✓ Passed**Advice** Front engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)**Notice** Items removed from driver's view prior to test**MOT #8** 2014-02-24 10:32**MOT test number** 768365354041**Result** ✓ Passed**MOT #7** 2013-02-28 11:50**MOT test number** 689579153089**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-03-26 12:23**MOT test number** 631938141413**Result** ✓ Passed**MOT #5** 2011-03-23 16:33**MOT test number** 406922481011**Result** ✓ Passed**MOT #4** 2010-03-19 10:48**MOT test number** 461388070085**Result** ✓ Passed

**MOT #3** 2010-03-15 10:31**MOT test number** 123314970024**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #2** 2009-03-19 11:28**MOT test number** 604458479076**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2009-03-19 10:13**MOT test number** 850158279089**Result** ✗ Failed**Fail** Centre Stop lamp not working (1.2.1b)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Parking brake lever has no reserve travel (3.1.6b)



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	LR06BFX
Plate since	2019-03-29
Current registration	LR06BFX
Plate since	2019-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-03-31
Last registration	2022-04-02
Complete history	See info



Registration #1	2006-03-31	7 mi
Registration #2	2009-03-19	23.227 mi
Registration #3	2009-03-19	23.227 mi
Registration #4	2010-03-15	323.064 mi
Registration #5	2010-03-19	32.119 mi
Registration #6	2011-03-23	40.604 mi
Registration #7	2012-03-26	49.069 mi
Registration #8	2013-02-28	56.881 mi
Registration #9	2014-02-24	65.485 mi
Registration #10	2015-03-20	75.277 mi
Registration #11	2016-03-20	85.277 mi
Registration #12	2017-03-20	95.277 mi
Registration #13	2018-03-20	105.277 mi
Registration #14	2019-03-20	115.277 mi
Registration #15	2020-03-20	125.277 mi
Registration #16	2021-03-20	135.277 mi
Registration #17	2022-03-20	145.277 mi
Registration #18	2022-04-02	155.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1447 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Engine number	K20A92003809