

Ford



General information

Make	FORD
Model	FOCUS TITANIUM
Colour	Silver
Year of manufacture	2010
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP	0 < 101 A
Max. torque	149 Nm at 4.000 rpm	101 - 120 ^B _C
Engine capacity	1.596 cc	121 - 140 P
Cylinders	4	141 - 165 F
Fuel type	Petrol	166 - 185 H
Consumption city	32.5 mpg	186 - 225 J
Consumption extra urban	51.4 mpg	225+ L
Consumption combined	42.2 mpg	
CO2 emission	159 g/km	
CO2 label	G	





Internet history

Entry 1

Date Pictures 2021-06-15

24

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-02
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	20
Total items failed	2

MOT #14		2023-05-03 13:03
MOT test number		246814591620
Result		✓ Passed
Next expiry date		2024-05-02
Advice Nearside Fro	ont Suspension arm pin or bush worn but not result	ing in excessive movement (5.3.4
Advice Nearside Fre	ont Suspension arm ball joint has slight play (5.3.4	(a) (i))
Advice Nearside Fre	ont Headlamp has a product on the light source but	not seriously reducing light output
Advice Offside From	nt Suspension arm pin or bush worn but not resultin	g in excessive movement (5.3.4 (a)
Advice Offside From	nt Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #13		2022-07-04 08:57
MOT test	number	666286208682
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #12		2021-07-27 15:57
MOT test	number	168343636123
Result		Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11		2020-06-10 09:48
MOT test	number	291473609287
Result		✓ Passed
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #10	2020-06-10 09:48
MOT test number	831739111927
Result	× Failed
Advice Nearside Front L	ower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Pass with rectification Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #9		2019-06-12 09:02
MOT test	number	419611339779
Result		✓ Passed
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #8	2018-06-12 09:17
MOT test number	344596113730
Result	✓ Passed





MOT #7	2018-06-12 09:17
MOT test number	166984154581
Result	🗙 Failed
Pass with rectification Offside Headlamp aim too high (4.1.2 (a))	
MOT #6	2017-06-13 09:01
MOT test number	637434964927
Result	✓ Passed
Advice Front wipers smearing	
Advice Items removed from driver's view prior to test	
Advice Offside Front Tyre worn close to the legal limit tyre bald inner edge (4.1.E.1)	

MOT #5	2016-06-13 11:30
MOT test number	213773216563
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #4	2015-06-19 11:50
MOT test number	247780475165
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components	

МОТ #3	2014-06-19 09:30
MOT test number	205830174129
Result	✓ Passed

МОТ #2	2013-06-21 14:58
MOT test number	638642073151
Result	✓ Passed





MOT #1	2013-02-06 08:47
MOT test number	918877733012
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ МОТ
Tax due: 1 July 2024	Expires: 2 May 2024
Tax status	Valid until 1 July
Days left	62
MOT expiry date	2 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-28
Last registration	2023-05-03
Complete history	<u>See info</u>



Registration #1	2010-03-28	26 mi
Registration #2	2013-02-06	13.452 mi
Registration #3	2013-06-21	14.107 mi
Registration #4	2014-06-19	27.501 mi
Registration #5	2015-06-19	39.718 mi
Registration #6	2016-06-13	52.964 mi
Registration #7	2017-06-13	64.603 mi
Registration #8	2018-06-12	75.001 mi
Registration #9		11.777 mi
Registration #9 Registration #10		00.000 est
		01.000 est 01.000 est 01.000 est
Registration #10		01,000 est 01,000 est 01,000 est 01,000 est
Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est
Registration #10 Registration #11 Registration #12		01,000 46 0,000 46 01,000 46 01,000 46 01,000 46 01,000 46
Registration #10 Registration #11 Registration #12 Registration #13		01,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46

More info >





Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1820 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	AS14346