



BD6ILZT

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI
Colour	Blue
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-18
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-30
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	12
Total items failed	10

MOT #16	2023-12-01 09:51
MOT test number	290544496308
Result	✓ Passed
Next expiry date	2024-11-30

MOT #15	2022-11-29 11:54
MOT test number	663486953721
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2021-11-04 12:40
MOT test number	491470108774
Result	✓ Passed

MOT #13	2021-11-03 15:05
MOT test number	553321343140
Result	✗ Failed
Fail	Rear Inner Anti-roll bar linkage pin or bush excessively worn d bush both sides (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge slight 3/4 wear (5.2.3 (e))
Advice	Front Oil leak, but not excessive engine (8.4.1 (a) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm 3/4 wear (5.2.3 (e))



MOT #12	2021-07-23 15:19
MOT test number	955289641889
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2020-06-26 16:07
MOT test number	271893785800
Result	✓ Passed

MOT #10	2020-06-26 10:36
MOT test number	163504227231
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #9	2019-04-13 13:49
MOT test number	959936592249
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8	2019-04-06 12:17
MOT test number	332180008869
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2018-05-01 13:57**MOT test number** 621825883964**Result** ✓ Passed**MOT #6** 2018-05-01 13:57**MOT test number** 192723830184**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #5** 2017-04-05 13:43**MOT test number** 341274933358**Result** ✓ Passed**MOT #4** 2016-09-12 13:51**MOT test number** 931338889884**Result** ✓ Passed**Advice** Covers fitted**MOT #3** 2015-10-17 09:28**MOT test number** 160533452344**Result** ✓ Passed**MOT #2** 2014-11-26 10:10**MOT test number** 645670834399**Result** ✓ Passed**Notice** Both front tyres slightly worn inner edge**Notice** Both front tyres 3mm



MOT #1	2014-11-26 09:35
MOT test number	519650834359
Result	✗ Failed
Fail	Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
Notice	Both front tyres slightly worn inner edge
Notice	Both front tyres 3mm



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
30 November 2024

Tax status	Valid until 1 May
------------	-------------------

Days left	3
-----------	---

MOT expiry date	30 November 2024
-----------------	------------------

Full MOT history	See MOT history
------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BD61LZT
Plate since	2019-06-29
Current registration	 BD61LZT
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-12-06
Last registration	2023-12-01
Complete history	See info



Registration #1	2011-12-06	14 mi
Registration #2	2014-11-26	9.300 mi
Registration #3	2014-11-26	9.300 mi
Registration #4	2015-10-17	12.185 mi
Registration #5	2016-09-12	18.067 mi
Registration #6	2017-04-05	20.502 mi
Registration #7	2018-05-01	31.999 mi
Registration #8	2018-05-01	31.999 mi
Registration #9	2019-04-06	38.777 mi
Registration #10	2019-04-06	38.777 mi
Registration #11	2019-04-06	38.777 mi
Registration #12	2019-04-06	38.777 mi
Registration #13	2019-04-06	38.777 mi
Registration #14	2019-04-06	38.777 mi
Registration #15	2019-04-06	38.777 mi
Registration #16	2019-04-06	38.777 mi
Registration #17	2019-04-06	38.777 mi
Registration #18	2019-04-06	38.777 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1841 mm
Length	4875 mm
Kerb weight	1560 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	CAY 511109