



report date: 2024-03-29

General information

| | |
|---------------------|-------------------------|
| Make | VOLVO |
| Model | V60 D4 BUSINESS EDITION |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 140 mph |
| 0 - 60 mph | 7.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 178 BHP |
| Max. torque | 400 Nm at 1.750 rpm |
| Engine capacity | 1.969 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 65.7 mpg |
| Consumption extra urban | 78.5 mpg |
| Consumption combined | 74.3 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-05-26 |
| Pictures | 37 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-12 |
| MOT pass rate | 78 % |
| MOT passed | 7 |
| Failed MOT tests | 2 |
| Total advice items | 15 |
| Total items failed | 3 |

| | |
|------------------|---|
| MOT #9 | 2024-02-13 11:05 |
| MOT test number | 691124926446 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-12 |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Front Steering system slightly rough top mounts (2.1.1 (a)) |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge 215/50r17 (5.2.3 (e)) |

| | |
|-----------------|--|
| MOT #8 | 2023-01-27 12:27 |
| MOT test number | 838817212125 |
| Result | ✓ Passed |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Engine covers and undertrays fitted |
| Advice | Suspension arm pin or bush worn but not resulting in excessive movement both front lower arm front bushes perished (5.3.4 (a) (i)) |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Minor | Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

**MOT #7** 2022-02-03 10:52**MOT test number** 463588017505**Result** ✓ Passed**MOT #6** 2021-02-02 16:09**MOT test number** 288585812160**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2021-02-02 16:09**MOT test number** 516062010276**Result** ✗ Failed**Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #4** 2020-02-03 11:35**MOT test number** 518490887248**Result** ✓ Passed**MOT #3** 2019-02-04 16:10**MOT test number** 807347974542**Result** ✓ Passed



| | |
|-----------------|--|
| MOT #2 | 2019-01-26 07:22 |
| MOT test number | 473954489261 |
| Result | ✗ Failed |
| Fail | Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |
| Fail | Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) |

| | |
|-----------------|------------------|
| MOT #1 | 2018-01-09 12:12 |
| MOT test number | 511418644990 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
12 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 12 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | DF64VUU |
| Plate since | 2019-03-29 |
| Current registration | DF64VUU |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2015-01-29 |
| Last registration | 2024-02-13 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2015-01-29 | 29 mi |
| Registration #2 | 2018-01-09 | 64.399 mi |
| Registration #3 | 2019-01-26 | 87.561 mi |
| Registration #4 | 2019-02-04 | 87.563 mi |
| Registration #5 | 2020-02-03 | 104.130 mi |
| Registration #6 | 2021-02-02 | 119.317 mi |
| Registration #7 | 2022-02-02 | 134.504 mi |
| Registration #8 | 2023-02-02 | 149.691 mi |
| Registration #9 | 2024-02-13 | 164.878 mi |
| Registration #10 | | |
| Registration #11 | | |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 94% |
| Children | 82% |
| Pedestrian | 64% |
| Safety systems | 100% |
| Overall rating | 86% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1865 mm |
| Height | 1484 mm |
| Length | 4635 mm |
| Wheel base | 2776 mm |
| Kerb weight | 1606 kg |
| Max. allowed weight | 2170 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 67 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1159399 |