





report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER EVOQUE R-DYN S D A S
Colour	Black
Year of manufacture	2019
Top speed	127 mph
Gearbox	9 speed automatic

Engine & fuel consumption

Power	178 BHP
Max. torque	430 Nm at 2.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	41.5 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2021-12-16

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-10-29

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



YB19SZW report date: 2024-03-28

MOT history

MOT expiry date	2025-04-03
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	22
Total items failed	0

MOT #4		2024-04-04 15:52
MOT test	number	535219560808
Result		✓ Passed
Next exp	ry date	2025-04-03
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps	or light sources (4.7.1
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords	s (5.2.3 (d) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor	Nearside Rear Direction indicator lens defective which has no effect on em	nitted light (4.4.1 (b) (i))
Advice	Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Position lamp lens defective which has no effect on emitted	d light
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Nail in tyre	
Minor	Nearside Stop lamp(s) lens defective which has no effect on emitted light	(4.3.1 (b) (i))
Advice	Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



Advice

Minor

YB19SZW

report date: 2024-03-28

MOT #3 2024-04-04 11:45 **MOT** test number 651431635394 Result × Failed **MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Rear Position lamp lens defective which has no effect on emitted light Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Rear Nail in tyre Minor Nearside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2	2023-02-16 17:13
MOT test number	989398207120
Result	✓ Passed

Nearside Stop lamp(s) lens defective which has no effect on emitted light (4.3.1 (b) (i))

Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

		•
MOT #1		2022-02-03 16:09
MOT test	number	141205620755
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	3 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.


Damage 1

Date	
Category	
Туре	

Damage 2

Category	
Date	
Damage 2	

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

\sim	
Owner	nictory
CVVIICI	IIISLUIV
~	,

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download	
2000000	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	SIE UK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-03-30
Last registration	2024-04-04
Complete history	See info



Registration #1	2019-03-30	25 mi
Registration #2		11.777 es
Registration #3		11.777 es
Registration #4	2022-02-03	23.294 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		D.377 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	86%
Children	75%
Pedestrian	41%
Safety systems	86%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	2100 mm
Height	1649 mm
Length	4371 mm
Wheel base	2681 mm
Kerb weight	1816 kg
Max. allowed weight	1948 kg

Additional information

Fuel tank capacity	54 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	190208W0320204DTD

CarCheck.co.uk page 11/11