





report date: 2024-03-28

General information

Make	CITROEN		
Model	BERLINGO 625 LX L1 HDI		
Colour	Red		
Year of manufacture	2008		
Top speed	99 mph		
0 - 60 mph	13.9 seconds		
Gearbox	5 speed Manual		

Engine & fuel consumption

Power	90 BHP	
Max. torque	215 Nm at 1.750 rpm	
Engine capacity	1.560 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	42.8 mpg	
Consumption extra urban	61.4 mpg	
Consumption combined	53.3 mpg	



CarCheck.co.uk page 1/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-01-30	
MOT pass rate	71 %	
MOT passed	12	
Failed MOT tests	5	
Total advice items	33	
Total items failed	3	

MOT #17	2023-01-30 10:00
MOT test number	651713454457
Result	✓ Passed
Next expiry date	2024-01-30
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice General corrosion to under body and components	

MOT #16		2022-01-31 16:11
MOT test	number	560567478033
Result		✓ Passed
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT #15 2022-01-27 17:51

MOT test number 468090905838

Result X Failed

MAJOR Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))

Advice Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MAJOR Front Oil leaking excessively from engine (8.4.1 (a) (i))

Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MAJOR Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Offside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))

MAJOR Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #14 2021-01-16 15:58

MOT test number 565244387127

Result ✓ Passed

MOT #13 2021-01-16 15:58

MOT test number 796854048674

Result X Failed

Pass with rectification Stop lamp(s) all not working switch (4.3.1 (a) (iii))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2019-10-25 13:53

MOT test number 389412197497

Result ✓ Passed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

rear (5.3.4 (a) (i))

MOT #11 2019-10-24 14:38

MOT test number 766582963060

Result X Failed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm 1.5 mm (5.2.3 (e))

MAJOR Offside Driver's view of an obligatory external mirror materially affected by an obstruction (3.1 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

MOT #10 2018-10-26 10:03

MOT test number 898192082748

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9 2018-10-23 11:20

MOT test number 841025633341

Result X Failed

MAJOR Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #8	2017-10-23 13:10
MOT test number	771710419696
Result	✓ Passed
Advice Offside brake peddle pad missing?	

MOT #7	2017-10-19 12:36
MOT test number	968511365446
Result	X Failed
Fail Offside Front Track rod end socket spring weak (2.2.B.1e)	
Fail Offside Registration plate lamp not working (1.1.C.1d)	
Advice Offside brake peddle pad missing?	

MOT #6		2016-10-12 08:54
MOT test	number	939175402914
Result		✓ Passed
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

·	•
MOT #5	2015-09-22 13:10
MOT test number	361880616047
Result	✓ Passed
MOT #4	2014-09-19 11:27
MOT test number	306732364482
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3	2013-09-17 16:30
MOT test number	667000163238
Result	✓ Passed
Notice Oil leak	

Notice Oil leak	
MOT #2	2012-09-26 10:08
MOT test number	428120772201
Result	✓ Passed
MOT #1	2011-09-23 12:35
MOT test number	998756361286
Result	✓ Passed

CarCheck.co.uk page 6/13



FG58HYY report date: 2024-03-28

Tax & MOT check





Expired: 30 January 2024

Tax status Expired at 1 January 2024

Days left 119 days too late

MOT expiry date 30 January 2024

Full MOT history See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



FG58HYY report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

\sim		ner	h	: -+		
	W/I	ıer	m	ısı	-0	IV

,		
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-30
Last registration	2023-01-30
Complete history	See info



Registration #1	2008-09-30	20 mi
Registration #2	2011-09-23	51.256 mi
Registration #3	2012-09-26	69.123 mi
Registration #4	2013-09-17	95.605 mi
Registration #5	2014-09-19	112.686 mi
Registration #6	2015-09-22	123.258 mi
Registration #7	2016-10-12	134.463 mi
Registration #8	2017-10-19	143.264 mi
Registration #9	2017-10-23	143.280 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		9.70 es
Registration #14		71.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 12/13



FG58HYY report date: 2024-03-28

Safety ratings

NCAP rating

Video <u>see crash video</u>

Dimensions & weight

 Width
 2112 mm

 Height
 1834 mm

 Length
 4380 mm

 Kerb weight
 1354 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBAC0011233

CarCheck.co.uk page 13/13