





General information

Make	CITROEN
Model	XSARA LX
Colour	Blue
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg





Internet history

Entry 1

Date

Pictures

2022-06-29

5

Listing price

View report



source: cargurus.co.uk



MOT history

МОТ #22	2021-07-21 15:49
MOT test number	304027199021
Result	✓ Passed
Next expiry date	2022-08-16
Advice Rear Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))	
Advice Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill both sides (6.2.2 (d) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge approx 2mm (5.2.	3 (e))
Advice Rear Brake pipe corroded, covered in grease or other material Both sides by (1.1.11 (c))	y flexi connections

MOT #21	2021-07-21 12:09	
MOT test number	564194909360	
Result	🗙 Failed	
Advice Offside Front Tyre worn close to legal limit/worn on edge approx 2mm (5	.2.3 (e))	
Advice Rear Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))		
Advice Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill both sides (6.2.2 (d) (i))		
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
Advice Rear Brake pipe corroded, covered in grease or other material Both sides (1.1.11 (c))	by flexi connections	

МОТ #20	2020-08-17 14:11
MOT test number	435592502858
Result	✓ Passed

Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Windscreen wiper blade defective (3.4 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))





MOT #19	2020-08-17 14:11
MOT test number	876875594898
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Windscreen wiper blade defective (3.4 (b) (i))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a)	(ii))

MOT #18		2019-08-02 10:27
MOT test	number	373143393798
Result		✓ Passed
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice	Exhaust mounting defective (6.1.2 (a))	

MOT #17	2018-08-15 15:10
MOT test number	633962210231
Result	✓ Passed

MOT #16	2017-07-26 11:05
MOT test number	322449720560
Result	✓ Passed





MOT #15	2016-08-16 16:27
MOT test number	164414011387
Result	✓ Passed
Advice Nearside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)	
MOT #14	2015-07-24 15:54
MOT test number	977915205263
Result	✓ Passed
MOT #13	2014-08-12 14:37
MOT test number	147534624239
Result	✓ Passed
Notice Nail in nearside rear tyre	
MOT #12	2013-07-23 12:19
MOT test number	238704803249
Result	✓ Passed
Notice Oil leak	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Middle exhaust corroded	





MOT #11	2013-07-16 16:06
MOT test number	346457893115
Result	🗙 Failed
Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)	
Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structur	e (4.1.D.1b)
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Oil leak	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach (4.1.D.1a)	the ply or cords
Notice Middle exhaust corroded	

MOT #10		2012-08-13 11:12
MOT test	number	326986122221
Result		✓ Passed
Notice	Front tyres wearing on edges	
Notice	Oil leak	
Notice	Rear tyres perished	
Notice	Nearside rear wiper end split	





MOT #9		2011-08-17 12:38
MOT test	number	266809421273
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)		
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice movement	Nearside Front Lower Suspension arm rubber bush deteriorated but not resul (2.4.G.2)	lting in excessive

MOT #8	2011-08-17 12:38		
MOT test number	949209321225		
Result	🗙 Failed		
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)			
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	Avice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		
Advice Exhaust has a minor leak of exhaust gases (7.1.2)			
Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)			
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)			
Pass with rectificationNearside Front position lamp(s) not working (1.1.A.3b)			





MOT #7		2011-01-24 17:36
MOT test	number	189064421418
Result		✓ Passed
Notice	Nail in offside rear tyre	
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice movemen	Offside Front Lower Suspension arm rubber bush deteriorated but not resultir (2.4.G.2)	ng in excessive
Notice	Front tyres wearing on inner edges	
Notice	Ns rear tyre slightly out of shape and starting to perish badly advise replacem	nent
Advice movemen	Nearside Front Lower Suspension arm rubber bush deteriorated but not result (2.4.G.2)	ting in excessive
Notice	Oil leak	





MOT #6	2011-01-24 09:37
MOT test number	959744021025
Result	🗙 Failed
Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in movement (2.4.G.2)	ו excessive
Notice Child seat fitted not allowing full inspection of adult belt	
Notice Front tyres wearing on inner edges	
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	
Notice Ns rear tyre slightly out of shape and starting to perish badly advise replacement	<u>:</u>
Fail Offside Front Valve stem seriously misaligned (4.1.D.1e)	
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting movement (2.4.G.2)	in excessive
Notice Oil leak	
Fail Offside Headlamp not working on dipped beam (1.7.5a)	
Notice Nail in offside rear tyre	
Fail Nearside Front Valve stem seriously misaligned (4.1.D.1e)	

MOT #5	2010-01-26 12:11
MOT test number	501036320037
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	





MOT #4		2009-01-28 10:37
MOT test	number	951028329054
Result		Passed
Notice	Os front tyre starting to perish badly wearing on outer edge and pressure low	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

МОТ #3	2007-09-10 11:20
MOT test number	890343557213
Result	✓ Passed
Notice Os rear tyre starting to perish badly	
Advice Rear Exhaust has part of the system slightly deteriorated (7.1.1a)	
Notice Nail in offside rear tyre	

MOT #2	2006-09-15 10:35
MOT test number	242258056242
Result	✓ Passed

MOT #1	2006-06-02 16:32
MOT test number	262743456175
Result	✓ Passed





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Damage 2	
Date	14 No. 10
Category	ame
Туре	

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-03-31
Last registration	2021-07-21
Complete history	<u>See info</u>



Registration #1	2003-03-31	29 mi
Registration #2	2006-06-02	34.585 mi
Registration #3	2006-09-15	34.640 mi
Registration #4	2007-09-10	41.727 mi
Registration #5	2009-01-28	51.667 mi
Registration #6	2010-01-26	58.997 mi
Registration #7	2011-01-24	67.874 mi
Registration #8	2011-01-24	67.874 mi
Registration #9	2011-08-17	68.094 mi
Registration #10	2012-08-13	72.171 mi
Registration #11	2013-07-16	75.474 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 mi
Registration #21		11. JUL 444





Safety ratings		
NCAP rating		
Video	see crash video	
Dimensions & weight		
Width		1975 mm
Height		1401 mm
Length		4167 mm
Wheel base		2540 mm
Kerb weight		1166 kg
Additional information		
Fuel tank capacity		55 I
Fuel delivery		Multi-Point Injection
Number of doors		5
Number of axles		2
Engine number		FSF84266756