



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	PRIUS VVT-I T3
Colour	Silver
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed CVT

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	56.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	65.7 mpg
CO2 emission	104 g/km
CO2 label	B





## Internet history

### Entry 4

Date 2023-07-13

Pictures 11

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 3

Date 2022-12-17

Pictures 20

Listing price [View report](#)




source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2

Date 2022-05-13

Pictures 20

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 1

Date 2021-02-05

CarCheck.co.uk

Pictures

10

Listing price

[View report](#)



source: [autoonline.co.uk](http://autoonline.co.uk)



## MOT history

MOT expiry date	2025-03-30
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	19
Total items failed	3

**MOT #17** 2024-03-22 15:32**MOT test number** 111692324667**Result** ✓ Passed**Next expiry date** 2025-03-30**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))**MOT #16** 2023-03-31 14:13**MOT test number** 584170486443**Result** ✓ Passed**Advice** Rear rear sub frame corroded**MOT #15** 2023-03-31 14:13**MOT test number** 184941248313**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Rear rear sub frame corroded**MOT #14** 2020-07-31 13:35**MOT test number** 243969836952**Result** ✓ Passed



MOT #13	2019-01-28 12:44
MOT test number	394679979276
Result	✓ Passed
MOT #12	2018-01-22 10:26
MOT test number	881713027773
Result	✓ Passed
MOT #11	2017-01-23 12:03
MOT test number	499086981530
Result	✓ Passed
MOT #10	2017-01-23 10:54
MOT test number	429338763694
Result	✗ Failed
<div><div>Fail</div>Offside Rear Brakes imbalanced across an axle (3.7.B.5b)</div>	

**MOT #9**

2016-01-19 10:06

**MOT test number**

560867438799

**Result**

✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear fuel pipes corroded
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Exhaust has a minor leak of exhaust gases Centre to rear joint (7.1.2)
- Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Cracking on both rear tyres
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Off side rear light unit cracked

**MOT #8**

2015-01-19 09:38

**MOT test number**

815369015071

**Result**

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #7**

2014-01-20 09:42

**MOT test number**

778090424090

**Result**

✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



<b>MOT #6</b>	2013-01-22 10:51
---------------	------------------

<b>MOT test number</b>	526432223054
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2012-01-17 13:38
---------------	------------------

<b>MOT test number</b>	137807712071
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2012-01-16 11:47
---------------	------------------

<b>MOT test number</b>	409116912030
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Nearside Rear coil spring cracked (2.4.C.1a)
-------------	--

<b>MOT #3</b>	2011-01-17 09:40
---------------	------------------

<b>MOT test number</b>	106157211042
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2010-01-18 15:09
---------------	------------------

<b>MOT test number</b>	120228510025
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2009-01-21 17:44
---------------	------------------

<b>MOT test number</b>	810711929071
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
30 March 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	30 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 10,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 10,50,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>GP55ZFZ</b>
Plate since	2019-09-29
Current registration	<b>GP55ZFZ</b>
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-02-15
Last registration	2024-03-22
Complete history	<a href="#">See info</a>



Registration #1	2006-02-15	9 mi
Registration #2	2009-01-21	38.381 mi
Registration #3	2010-01-18	51.396 mi
Registration #4	2011-01-17	66.549 mi
Registration #5	2012-01-16	76.976 mi
Registration #6	2012-01-17	76.976 mi
Registration #7	2013-01-22	85.203 mi
Registration #8	2014-01-20	93.338 mi
Registration #9	2015-01-19	100.715 mi
Registration #10	2016-01-19	108.731 mi
Registration #11	2017-01-23	112.156 mi
Registration #12	2018-01-23	112.156 mi
Registration #13	2019-01-23	112.156 mi
Registration #14	2020-01-23	112.156 mi
Registration #15	2021-01-23	112.156 mi
Registration #16	2022-01-23	112.156 mi
Registration #17	2023-01-23	112.156 mi
Registration #18	2024-01-23	112.156 mi
Registration #19	2025-01-23	112.156 mi
Registration #20	2026-01-23	112.156 mi
Registration #21	2027-01-23	112.156 mi
Registration #22	2028-01-23	112.156 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1325 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1NZ4201111