



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D3 SE
Colour	Grey
Year of manufacture	2012
Top speed	137 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	68.9 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-07-24
Pictures	19
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-07-23
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-03
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	18
Total items failed	11

MOT #13 2024-04-12 14:59

MOT test number 991634397652

Result ✗ Failed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Innermost bush deteriorating (5.3.4 (a) (i))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Innermost bush deteriorating (5.3.4 (a) (i))
- Fail** Horn not working (7.7 (a))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake binding - not excessively
- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

MOT #12 2023-04-04 08:40

MOT test number 270936673692

Result ✓ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #11** 2021-10-21 16:16**MOT test number** 791576098312**Result** ✓ Passed**MOT #10** 2020-11-30 16:12**MOT test number** 702077133675**Result** ✓ Passed**MOT #9** 2020-11-27 11:15**MOT test number** 719797515593**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2019-12-04 13:33**MOT test number** 681640172021**Result** ✓ Passed**Advice** Rear Shock absorbers light misting of oil or has limited damping effect on both sides (5.3.2 (b))**MOT #7** 2019-12-04 13:33**MOT test number** 793052429236**Result** ✗ Failed**Advice** Rear Shock absorbers light misting of oil or has limited damping effect on both sides (5.3.2 (b))**Pass with rectification** Rear Tyre tread depth below requirements of 1.6mm both sides (5.2.3 (e))**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #6** 2018-12-19 12:58**MOT test number** 919446246793**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2017-12-22 09:25**MOT test number** 748274800286**Result** ✓ Passed**MOT #4** 2016-10-29 12:28**MOT test number** 314445691191**Result** ✓ Passed**MOT #3** 2016-10-29 12:28**MOT test number** 706485895062**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #2** 2015-10-06 14:46**MOT test number** 737644851863**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)



MOT #12015-09-30 13:39

MOT test number515008499520

ResultX Failed

- Fail

Front registration plate deteriorated (6.3.1d)
- Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)
- Fail

Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Fail

Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✗
MOT
Expired:
3 April 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	3 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-09-20
Last registration	2024-04-12
Complete history	See info



Registration #1	2012-09-20	13 mi
Registration #2	2015-09-30	96.583 mi
Registration #3	2015-10-06	96.588 mi
Registration #4	2016-10-29	104.313 mi
Registration #5	2016-10-29	104.313 mi
Registration #6	2017-12-22	112.681 mi
Registration #7	2018-12-19	123.278 mi
Registration #8	2019-12-04	129.183 mi
Registration #9	2020-05-20	131.277 mi
Registration #10	2020-05-20	131.277 mi
Registration #11	2020-05-20	131.277 mi
Registration #12	2020-05-20	131.277 mi
Registration #13	2020-05-20	131.277 mi
Registration #14	2020-05-20	131.277 mi
Registration #15	2020-05-20	131.277 mi
Registration #16	2020-05-20	131.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1574 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1099062