



report date: 2024-03-28

General information

Make	MINI
Model	COOPER SD
Colour	White
Year of manufacture	2013
Top speed	130 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-04-17
Pictures	47
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-15
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	15
Total items failed	0

MOT #10	2023-08-22 15:02
MOT test number	368259883086
Result	✓ Passed
Next expiry date	2024-09-15

MOT #9	2023-08-18 10:09
MOT test number	752224198556
Result	✗ Failed
<b>DANGEROUS</b> Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
<b>MAJOR</b> Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
<b>DANGEROUS</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #8	2022-09-16 13:31
MOT test number	557438878014
Result	✓ Passed

MOT #7	2022-09-12 13:02
MOT test number	583503387695
Result	✗ Failed
<b>MAJOR</b> Offside Rear Service brake excessively binding (1.2.1 (f))	
<b>MAJOR</b> Nearside Rear Service brake excessively binding (1.2.1 (f))	

**MOT #6** 2021-07-13 07:58**MOT test number** 245969772117**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and perished (5.2.3 (e))**MOT #5** 2020-07-24 11:37**MOT test number** 971198374201**Result** ✓ Passed**Advice** Offside Rear Road wheel slightly distorted inner bead (5.2.2 (c) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Road wheel slightly distorted inner bead (5.2.2 (c) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #4** 2019-08-02 12:29**MOT test number** 141250098529**Result** ✓ Passed**MOT #3** 2018-09-18 14:59**MOT test number** 247365269167**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #2	2017-09-26 13:44
MOT test number	440334769033
Result	✓ Passed

  

MOT #1	2016-09-21 08:13
MOT test number	834004155046
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
15 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	15 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-26
Last registration	2023-08-22
Complete history	<a href="#">See info</a>



Registration #1	2013-09-26	28 mi
Registration #2	2016-09-21	41.352 mi
Registration #3	2017-09-26	46.360 mi
Registration #4	2018-09-18	54.205 mi
Registration #5	2019-08-02	55.442 mi
Registration #6	2020-07-24	56.575 mi
Registration #7	2020-08-22	56.575 mi
Registration #8	2020-08-22	56.575 mi
Registration #9	2020-08-22	56.575 mi
Registration #10	2020-08-22	56.575 mi
Registration #11	2020-08-22	56.575 mi
Registration #12	2020-08-22	56.575 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1150 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	70798418
---------------	----------